

## 2004 Chevrolet Tahoe

All TSBs

OEM REF NO	TITLE	PUB DATE
00-00-89-008	RECREATIONAL (DINGHY) TOWING	2006-07-28
00-00-89-008A	RECREATIONAL (DINGHY) TOWING	2006-07-28
00-00-89-008B	RECREATIONAL (DINGHY) TOWING	2006-07-28
00-00-89-008C	RECREATIONAL (DINGHY) TOWING	2006-07-28
00-00-89-008D	RECREATIONAL (DINGHY) TOWING	2006-07-28
00-00-89-008E	RECREATIONAL (DINGHY) TOWING	2006-07-28
00-00-89-008F	RECREATIONAL (DINGHY) TOWING	2006-07-28
00-00-89-027	ELIMINATING UNWANTED ODORS IN VEHICLES	2005-10-25
00-00-89-027	ELIMINATING UNWANTED ODORS IN VEHICLES	2006-10-01
00-00-89-027A	ELIMINATING UNWANTED ODORS IN VEHICLES	2005-10-25
00-00-89-027A	ELIMINATING UNWANTED ODORS IN VEHICLES	2006-10-01
00-00-89-027B	ELIMINATING UNWANTED ODORS IN VEHICLES	2005-10-25
00-00-89-027B	ELIMINATING UNWANTED ODORS IN VEHICLES	2006-10-01
00-00-89-027C	ELIMINATING UNWANTED ODORS IN VEHICLES	2005-10-25
00-00-89-027D	ELIMINATING UNWANTED ODORS IN VEHICLES	2006-10-01
00-00-90-002	INFORMATION ON PROPER TIRE PRESSURE	2006-08-22
00-00-90-002A	INFORMATION ON PROPER TIRE PRESSURE	2006-08-22
00-00-90-002B	INFORMATION ON PROPER TIRE PRESSURE	2006-08-22
00-00-90-002C	INFORMATION ON PROPER TIRE PRESSURE	2006-08-22
00-00-90-002D	INFORMATION ON PROPER TIRE PRESSURE	2006-08-22
00-02-305-003A	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003A	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003B	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003C	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003D	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003E	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003F	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003G	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003H	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003I	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003J	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-02-35-003K	CLUNKING NOISE UNDER HOOD AND CAN BE FELT IN THE STEERING WHEEL AND/OR STEERING COLUMN	2006-08-18
00-03-10-002	CHEMICAL STAINING, PITTING, CORROSION AND/OR SPOTTED APPEARANCE OF CHROMED ALUMINUM WHEELS	2006-08-01
00-03-10-002A	CHEMICAL STAINING, PITTING, CORROSION AND/OR SPOTTED APPEARANCE OF CHROMED ALUMINUM WHEELS	2006-08-01
00-03-10-002B	CHEMICAL STAINING, PITTING, CORROSION AND/OR SPOTTED APPEARANCE OF CHROMED ALUMINUM WHEELS	2006-08-01
00-03-10-002C	CHEMICAL STAINING, PITTING, CORROSION AND/OR SPOTTED APPEARANCE OF CHROMED ALUMINUM WHEELS	2006-08-01
	CHEMICAL STAINING, PITTING, CORROSION AND/OR SPOTTED	

XXX

Saturday, October 10, 2009 1:34:46 AM

Page 1

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

00-03-10-002D	APPEARANCE OF CHROMED ALUMINUM WHEELS	2006-08-01
00-03-10-003	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003A	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003B	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003C	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003D	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003E	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003F	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003G	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003H	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-003I	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
00-03-10-006	INFORMATION ON TIRE RADIAL FORCE VARIATION (RFV)	2005-06-17
00-03-10-006A	INFORMATION ON TIRE RADIAL FORCE VARIATION (RFV)	2005-06-17
00-05-22-002	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002A	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002B	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002C	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002D	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002E	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002F	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002G	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-05-22-002H	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
00-06-01-012	USE OF SURFACE CONDITIONING DISKS	2006-01-18
00-06-01-012A	USE OF SURFACE CONDITIONING DISKS	2006-01-18
00-06-01-012B	USE OF SURFACE CONDITIONING DISKS	2006-01-18
00-06-01-026	INTAKE MANIFOLD INSPECTION/REPLACEMENT AFTER SEVERE INTERNAL ENGINE DAMAGE	2004-06-14
00-06-01-026A	INTAKE MANIFOLD INSPECTION/REPLACEMENT AFTER SEVERE INTERNAL ENGINE DAMAGE	2004-06-14
00-06-02-006	DEX-COOL ENGINE COOLANT INFORMATION	2005-02-13
00-06-02-006A	DEX-COOL ENGINE COOLANT INFORMATION	2005-02-13
00-06-02-006B	ENGINE COOLANT RECYCLING AND WARRANTY INFORMATION	2006-08-15
00-06-02-006C	ENGINE COOLANT RECYCLING AND WARRANTY INFORMATION	2006-08-15
00-06-02-006D	ENGINE COOLANT RECYCLING AND WARRANTY INFORMATION	2006-08-15
00-06-03-003	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
00-06-04-033	I/M READINESS AS PART OF EMISSION INSPECTION AND MAINTENANCE PROGRAM FOR OBD II VEHICLES	2006-10-10
00-06-04-033A	I/M READINESS AS PART OF EMISSION INSPECTION AND MAINTENANCE PROGRAM FOR OBD II VEHICLES	2006-10-10
00-06-04-033B	I/M READINESS AS PART OF EMISSION INSPECTION AND MAINTENANCE PROGRAM FOR OBD II VEHICLES	2006-10-10
00-07-30-009	CURRENT MODEL YEAR GOODWRENCH TRANSMISSION REPLACEMENT ASSEMBLY PROGRAM	2006-10-10
00-07-30-009A	CURRENT MODEL YEAR GOODWRENCH TRANSMISSION REPLACEMENT ASSEMBLY PROGRAM	2006-10-10
00-07-30-009B	CURRENT MODEL YEAR GOODWRENCH TRANSMISSION REPLACEMENT ASSEMBLY PROGRAM	2006-10-10
00-07-30-022	NO REVERSE, SECOND GEAR OR FOURTH GEAR (REPLACE REACTION SUN SHELL WITH MORE ROBUST HEAT TREATED PARTS)	2004-12-10
00-07-30-022A	NO REVERSE, SECOND GEAR OR FOURTH GEAR (REPLACE REACTION SUN SHELL WITH MORE ROBUST HEAT TREATED PARTS)	2004-12-10
NO REVERSE, SECOND GEAR OR FOURTH GEAR (REPLACE		

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 2

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

00-07-30-022B	REACTION SUN SHELL WITH MORE ROBUST HEAT TREATED PARTS)	2004-12-10
00-07-30-022C	NO REVERSE, SECOND GEAR OR FOURTH GEAR (REPLACE REACTION SUN SHELL WITH MORE ROBUST HEAT TREATED PARTS)	2004-12-10
00-08-46-002	ONSTAR SYSTEM CELLULAR ANTENNA REPLACEMENT PARTS AVAILABILITY	2005-04-12
00-08-46-002A	ONSTAR SYSTEM CELLULAR ANTENNA REPLACEMENT PARTS AVAILABILITY	2005-04-12
00-08-46-003	GLOBAL POSITION SENSOR (GPS) PERFORMANCE DEGRADATION	2005-02-09
00-08-46-003A	GLOBAL POSITION SENSOR (GPS) PERFORMANCE DEGRADATION	2005-02-09
00-08-46-003B	GLOBAL POSITION SENSOR (GPS) PERFORMANCE DEGRADATION	2005-02-09
00-08-48-005	DISTORTION IN OUTER SURFACE OF VEHICLE GLASS	2006-09-12
00-08-48-005A	DISTORTION IN OUTER SURFACE OF VEHICLE GLASS	2006-09-12
00-08-48-005B	DISTORTION IN OUTER SURFACE OF VEHICLE GLASS	2006-09-12
01-00-89-010A	INFORMATION ON USE OF DIAGNOSTIC WORKSHEET	2006-07-19
01-00-89-010B	INFORMATION ON USE OF DIAGNOSTIC WORKSHEET	2006-07-19
01-01-38-006	CONTAMINATED R-134A A/C SYSTEMS - AIR CONDITIONING SYSTEM FLUSHING PROCEDURES AND UNIVERSAL IN-LINE A/C FILETER INSTALLATION	2004-09-14
01-01-38-006A	CONTAMINATED R-134A A/C SYSTEMS - AIR CONDITIONING SYSTEM FLUSHING PROCEDURES AND UNIVERSAL IN-LINE A/C FILETER INSTALLATION	2004-09-14
01-01-38-006B	CONTAMINATED R-134A A/C SYSTEMS - AIR CONDITIONING SYSTEM FLUSHING PROCEDURES AND UNIVERSAL IN-LINE A/C FILETER INSTALLATION	2004-09-14
01-01-38-006C	CONTAMINATED R-134A A/C SYSTEMS - AIR CONDITIONING SYSTEM FLUSHING PROCEDURES AND UNIVERSAL IN-LINE A/C FILETER INSTALLATION	2004-09-14
01-01-38-006D	CONTAMINATED R-134A A/C SYSTEMS - AIR CONDITIONING SYSTEM FLUSHING PROCEDURES AND UNIVERSAL IN-LINE A/C FILETER INSTALLATION	2004-09-14
01-01-38-013	DIAGNOSTIC INFORMATION TO CONSIDER BEFORE AIR CONDITIONING COMPRESSOR REPLACEMENT	2001-12-01
01-01-38-013A	DIAGNOSTIC INFORMATION TO CONSIDER BEFORE AIR CONDITIONING COMPRESSOR REPLACEMENT	2001-12-01
01-01-39-003	J 44551 A/C SUCTION SCREEN KIT REPAIR RECOMMENDATIONS AND PROCEDURES AFTER CATASTROPHIC COMPRESSOR FAILURES	2003-07-01
01-01-39-003A	J 44551 A/C SUCTION SCREEN KIT REPAIR RECOMMENDATIONS AND PROCEDURES AFTER CATASTROPHIC COMPRESSOR FAILURES	2003-07-01
01-03-10-009	PLASTIC WHEEL NUT COVERS MISSING AND/OR LOOSE (REPLACE MISSING COVERS AND ADD SEALANT TO ALL COVERS)	2004-07-27
01-03-10-009A	PLASTIC WHEEL NUT COVERS MISSING AND/OR LOOSE (REPLACE MISSING COVERS AND ADD SEALANT TO ALL COVERS)	2004-07-27
01-04-18-001	DRIVELINE CHARACTERISTICS FOR ALL-WHEEL DRIVE (AWD) AND FOUR-WHEEL DRIVE (4WD) SYSTEMS	2006-05-09
01-04-18-001A	DRIVELINE CHARACTERISTICS FOR ALL-WHEEL DRIVE (AWD) AND FOUR-WHEEL DRIVE (4WD) SYSTEMS	2006-05-09
01-04-18-001B	DRIVELINE CHARACTERISTICS FOR ALL-WHEEL DRIVE (AWD) AND FOUR-WHEEL DRIVE (4WD) SYSTEMS	2006-05-09
01-04-18-001C	DRIVELINE CHARACTERISTICS FOR ALL-WHEEL DRIVE (AWD) AND FOUR-WHEEL DRIVE (4WD) SYSTEMS	2006-05-09

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 3

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

01-04-18-001D	DRIVELINE CHARACTERISTICS FOR ALL-WHEEL DRIVE (AWD) AND FOUR-WHEEL DRIVE (4WD) SYSTEMS	2006-05-09
01-04-18-001E	DRIVELINE CHARACTERISTICS FOR ALL-WHEEL DRIVE (AWD) AND FOUR-WHEEL DRIVE (4WD) SYSTEMS	2006-05-09
01-05-26-001	LOW EFFORT PARKING BRAKE APPLY SYSTEM	2005-04-08
01-05-26-001A	LOW EFFORT PARKING BRAKE APPLY SYSTEM	2005-04-08
01-06-01-011	INFORMATION ON ENGINE OIL CONSUMPTION GUIDELINES	2005-08-01
01-06-01-011A	INFORMATION ON ENGINE OIL CONSUMPTION GUIDELINES	2005-08-01
01-06-01-011B	INFORMATION ON ENGINE OIL CONSUMPTION GUIDELINES	2005-08-01
01-07-30-002A	MALFUNCTION INDICATOR LAMP (MIL) ON, TRANSMISSION STUCK IN SECOND OR THIRD GEAR, INSTRUMENT CLUSTER INOPERATIVE (VERIFY AND REPAIR SOURCE OF VOLTAGE LOSS IN TRANSMISSION SOLENOID POWER SUPPLY CIRCUIT)	2005-09-23
01-07-30-002B	MALFUNCTION INDICATOR LAMP (MIL) ON, TRANSMISSION STUCK IN SECOND OR THIRD GEAR, INSTRUMENT CLUSTER INOPERATIVE (VERIFY AND REPAIR SOURCE OF VOLTAGE LOSS IN TRANSMISSION SOLENOID POWER SUPPLY CIRCUIT)	2005-09-23
01-07-30-002C	MALFUNCTION INDICATOR LAMP (MIL) ON, TRANSMISSION STUCK IN SECOND OR THIRD GEAR, INSTRUMENT CLUSTER INOPERATIVE (VERIFY AND REPAIR SOURCE OF VOLTAGE LOSS IN TRANSMISSION SOLENOID POWER SUPPLY CIRCUIT)	2005-09-23
01-07-30-002D	MALFUNCTION INDICATOR LAMP (MIL) ON, TRANSMISSION STUCK IN SECOND OR THIRD GEAR, INSTRUMENT CLUSTER INOPERATIVE (VERIFY AND REPAIR SOURCE OF VOLTAGE LOSS IN TRANSMISSION SOLENOID POWER SUPPLY CIRCUIT)	2005-09-23
01-07-30-002E	MALFUNCTION INDICATOR LAMP (MIL) ON, TRANSMISSION STUCK IN SECOND OR THIRD GEAR, INSTRUMENT CLUSTER INOPERATIVE (VERIFY AND REPAIR SOURCE OF VOLTAGE LOSS IN TRANSMISSION SOLENOID POWER SUPPLY CIRCUIT)	2005-09-23
01-07-30-010	AUTOMATIC TRANSMISSION/TRANSAXLE TORQUE CONVERTER REPLACEMENT	2005-10-11
01-07-30-010A	AUTOMATIC TRANSMISSION/TRANSAXLE TORQUE CONVERTER REPLACEMENT	2005-10-11
01-07-30-010B	AUTOMATIC TRANSMISSION/TRANSAXLE TORQUE CONVERTER REPLACEMENT	2005-10-11
01-07-30-030	4L60-E/4L65-E AUTOMATIC TRANSMISSION DIAGNOSTIC INFORMATION ON HARSH 1-2 UPSHIFT	2005-10-18
01-07-30-030A	4L60-E/4L65-E AUTOMATIC TRANSMISSION DIAGNOSTIC INFORMATION ON HARSH 1-2 UPSHIFT	2005-10-18
01-07-30-030B	4L60-E/4L65-E AUTOMATIC TRANSMISSION DIAGNOSTIC INFORMATION ON HARSH 1-2 UPSHIFT	2005-10-18
01-07-30-031	1-2, 2-3, 3-4, 4-5 SHIFT AND TORQUE CONVERTER CLUTCH (TCC) CHARACTERISTICS DURING COLD WEATHER OPERATION ON 4L60-E, 4L80-E OR ALLISON TRANSMISSIONS	2004-02-25
01-07-30-031A	1-2, 2-3, 3-4, 4-5 SHIFT AND TORQUE CONVERTER CLUTCH (TCC) CHARACTERISTICS DURING COLD WEATHER OPERATION ON 4L60-E, 4L80-E OR ALLISON TRANSMISSIONS	2004-02-25
01-07-30-032	TRANSMISSION OIL LEAKING FROM TRANSMISSION VENT	2006-10-30
01-07-30-032A	TRANSMISSION OIL LEAKING FROM TRANSMISSION VENT	2006-10-30
01-07-30-032B	TRANSMISSION OIL LEAKING FROM TRANSMISSION VENT	2006-10-30
01-07-30-032C	TRANSMISSION OIL LEAKING FROM TRANSMISSION VENT	2006-10-30
01-07-30-032D	TRANSMISSION OIL LEAKING FROM TRANSMISSION VENT	2006-10-30
01-07-30-036	DIAGNOSTIC TIPS FOR AUTOMATIC TRANSMISSION DTC P0756, SECOND, THIRD, FOURTH GEAR START	2006-02-14
01-07-30-036A	DIAGNOSTIC TIPS FOR AUTOMATIC TRANSMISSION DTC P0756, SECOND, THIRD, FOURTH GEAR START	2006-02-14
01-07-30-036B	DIAGNOSTIC TIPS FOR AUTOMATIC TRANSMISSION DTC P0756, SECOND, THIRD, FOURTH GEAR START	2006-02-14

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 4

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

01-07-30-036C	DIAGNOSTIC TIPS FOR AUTOMATIC TRANSMISSION DTC P0756, SECOND, THIRD, FOURTH GEAR START	2006-02-14
01-07-30-036D	DIAGNOSTIC TIPS FOR AUTOMATIC TRANSMISSION DTC P0756, SECOND, THIRD, FOURTH GEAR START	2006-02-14
01-07-30-036E	DIAGNOSTIC TIPS FOR AUTOMATIC TRANSMISSION DTC P0756, SECOND, THIRD, FOURTH GEAR START	2006-02-14
01-07-30-036F	DIAGNOSTIC TIPS FOR AUTOMATIC TRANSMISSION DTC P0756, SECOND, THIRD, FOURTH GEAR START	2006-02-14
01-07-30-038	DIAGNOSTIC TROUBLE CODE (DTC) P0757 SET, MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED, POOR PERFORMANCE OF TRANSMISSION, TRANSMISSION SLIPPING	2006-09-12
01-07-30-038A	DIAGNOSTIC TROUBLE CODE (DTC) P0757 SET, MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED, POOR PERFORMANCE OF TRANSMISSION, TRANSMISSION SLIPPING	2006-09-12
01-07-30-038B	DIAGNOSTIC TROUBLE CODE (DTC) P0757 SET, MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED, POOR PERFORMANCE OF TRANSMISSION, TRANSMISSION SLIPPING	2006-09-12
01-07-30-038C	DIAGNOSTIC TROUBLE CODE (DTC) P0757 SET, MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED, POOR PERFORMANCE OF TRANSMISSION, TRANSMISSION SLIPPING	2006-09-12
01-07-30-038D	DIAGNOSTIC TROUBLE CODE (DTC) P0757 SET, MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED, POOR PERFORMANCE OF TRANSMISSION, TRANSMISSION SLIPPING	2006-09-12
01-07-30-041	TRANSMISSION FLUID LEAK DIAGNOSIS	2005-10-06
01-07-30-041A	TRANSMISSION FLUID LEAK DIAGNOSIS	2005-10-06
01-07-30-041B	TRANSMISSION FLUID LEAK DIAGNOSIS	2005-10-06
01-07-30-042	INFORMATION ON 2-3 UPSHIFT OR 3-2 DOWNSHIFT CLUNK NOISE	2006-05-16
01-07-30-042A	INFORMATION ON 2-3 UPSHIFT OR 3-2 DOWNSHIFT CLUNK NOISE	2006-05-16
01-07-30-042B	INFORMATION ON 2-3 UPSHIFT OR 3-2 DOWNSHIFT CLUNK NOISE	2006-05-16
01-07-30-042C	INFORMATION ON 2-3 UPSHIFT OR 3-2 DOWNSHIFT CLUNK NOISE	2006-05-16
01-07-30-042D	INFORMATION ON 2-3 UPSHIFT OR 3-2 DOWNSHIFT CLUNK NOISE	2006-05-16
01-08-51-003	APPLICATION OF ANTI-CORROSION MATERIALS	2004-07-23
01-08-51-003A	APPLICATION OF ANTI-CORROSION MATERIALS	2004-07-23
01-08-97-001	HOMELINK TRANSCEIVER/GARAGE DOOR OPENER TRANSMITTER TEST KIT	2003-07-14
01-08-97-001A	HOMELINK TRANSCEIVER/GARAGE DOOR OPENER TRANSMITTER TEST KIT	2003-07-14
01-08-97-001B	HOMELINK TRANSCEIVER/GARAGE DOOR OPENER TRANSMITTER TEST KIT	2003-07-14
02-00-89-002E	INFORMATION FOR DEALERS ON HOW TO SUBMIT A FIELD PRODUCT REPORT	2006-10-26
02-00-89-002F	INFORMATION FOR DEALERS ON HOW TO SUBMIT A FIELD PRODUCT REPORT	2006-10-26
02-00-89-006	NEW ADD TIME FOR LABOR OPERATION L2300 - CONVERTER, OXIDATION CATALYTIC-REPLACE	2005-12-22
02-00-89-006A	NEW ADD TIME FOR LABOR OPERATION L2300 - CONVERTER, OXIDATION CATALYTIC-REPLACE	2005-12-22
02-00-89-006B	NEW ADD TIME FOR LABOR OPERATION L2300 - CONVERTER, OXIDATION CATALYTIC-REPLACE	2005-12-22
02-00-89-006C	NEW ADD TIME FOR LABOR OPERATION L2300 - CONVERTER, OXIDATION CATALYTIC-REPLACE	2005-12-22
02-00-89-007	LIGHT AND MEDIUM DUTY TRUCK WARRANTY AND CROSSLINE WARRANTY ELIGIBILITY AND GUIDLINES FOR CHEVROLET AND	2006-08-04

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 5

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

GMC DEALERS		
02-00-89-007A	LIGHT AND MEDIUM DUTY TRUCK WARRANTY AND CROSSLINE WARRANTY ELIGIBILITY AND GUIDLINES FOR CHEVROLET AND GMC DEALERS	2006-08-04
02-00-89-014A	NEW LABOR OPERATION CODES FOR DEALER-INSTALLED GM ACCESSORIES REPLACED DURING WARRANTY COVERAGE PERIOD	2006-09-07
02-01-39-004	NEW PAG OIL RELEASED	2005-11-16
02-01-39-004A	NEW PAG OIL RELEASED	2005-11-16
02-01-39-004B	NEW PAG OIL RELEASED	2005-11-16
02-01-39-007	AUTOMATIC DUAL ZONE HVAC BATTERY DRAW	2004-08-17
02-01-39-007A	AUTOMATIC DUAL ZONE HVAC BATTERY DRAW	2004-08-17
02-03-07-002A	REVISED FRONT CASTER AND CAMBER ADJUSTMENT PROCEDURE	2005-03-24
02-03-10-001	INFO - SPARE TIRE IS A DIFFERENT SIZE THAN OTHER TIRES	2006-08-28
02-03-10-001A	INFO - SPARE TIRE IS A DIFFERENT SIZE THAN OTHER TIRES	2006-08-28
02-03-10-001B	INFO - SPARE TIRE IS A DIFFERENT SIZE THAN OTHER TIRES	2006-08-28
02-03-10-001C	INFO - SPARE TIRE IS A DIFFERENT SIZE THAN OTHER TIRES	2006-08-28
02-04-21-006	INOPERATIVE 4WD/AWD OR SERVICE 4WD INDICATOR	2004-03-01
02-04-21-006A	INOPERATIVE 4WD/AWD OR SERVICE 4WD INDICATOR	2004-03-01
02-04-21-006B	INOPERATIVE 4WD/AWD OR SERVICE 4WD INDICATOR	2004-03-01
02-04-21-006C	INOPERATIVE 4WD/AWD OR SERVICE 4WD INDICATOR	2004-03-01
02-04-21-006D	INOPERATIVE 4WD/AWD OR SERVICE 4WD INDICATOR	2004-03-01
02-04-21-006D	INOPERATIVE 4WD/AWD LAMPS, INOPERATIVE 4WD/AWD SYSTEM, DTC C0550 SET, NO COMMUNICATION WITH TCCM	2006-07-20
02-04-21-006E	INOPERATIVE 4WD/AWD LAMPS, INOPERATIVE 4WD/AWD SYSTEM, DTC C0550 SET, NO COMMUNICATION WITH TCCM	2006-07-20
02-05-22-004	TRAILER BRAKES APPLIED WHEN HEADLIGHTS/PARK LAMPS ARE ON, BRAKE CONTROLLER ILLUMINATION (MODIFY BRAKE CONTROLLER WIRING HARNESS)	2005-04-05
02-05-22-004A	TRAILER BRAKES APPLIED WHEN HEADLIGHTS/PARK LAMPS ARE ON, BRAKE CONTROLLER ILLUMINATION (MODIFY BRAKE CONTROLLER WIRING HARNESS)	2005-04-05
02-05-22-004B	TRAILER BRAKES APPLIED WHEN HEADLIGHTS/PARK LAMPS ARE ON, BRAKE CONTROLLER ILLUMINATION (MODIFY BRAKE CONTROLLER WIRING HARNESS)	2005-04-05
02-05-22-004C	TRAILER BRAKES APPLIED WHEN HEADLIGHTS/PARK LAMPS ARE ON, BRAKE CONTROLLER ILLUMINATION (MODIFY BRAKE CONTROLLER WIRING HARNESS)	2005-04-05
02-05-26-001	INFO - REAR PARKING BRAKE SHOE RETAINING SPRING CLIP SERVICE KIT FOR DRUM-IN-HAT (DIH) EQUIPPED VEHICLES	2005-01-19
02-05-26-001A	INFO - REAR PARKING BRAKE SHOE RETAINING SPRING CLIP SERVICE KIT FOR DRUM-IN-HAT (DIH) EQUIPPED VEHICLES	2005-01-19
02-05-26-001B	INFO - REAR PARKING BRAKE SHOE RETAINING SPRING CLIP SERVICE KIT FOR DRUM-IN-HAT (DIH) EQUIPPED VEHICLES	2005-01-19
02-05-26-001C	INFO - REAR PARKING BRAKE SHOE RETAINING SPRING CLIP SERVICE KIT FOR DRUM-IN-HAT (DIH) EQUIPPED VEHICLES	2005-01-19
02-06-03-006	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
02-06-03-006A	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
02-06-03-006B	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
02-06-03-008	LOW VOLTAGE DISPLAY ON IP GAUGE, LIGHTS DIM AT STOP LIGHTS, BATTERY DISCHARGED, NO START, SLOW CRANKING, DIM LIGHTS AT IDLE, LOW GENERATOR OUTPUT	2004-07-28
02-06-03-008A	LOW VOLTAGE DISPLAY ON IP GAUGE, LIGHTS DIM AT STOP LIGHTS, BATTERY DISCHARGED, NO START, SLOW CRANKING,	2004-07-28

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 6

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

DIM LIGHTS AT IDLE, LOW GENERATOR OUTPUT		
02-06-03-010	BATTERY PARASITIC DRAIN	2004-07-02
02-06-03-010A	BATTERY PARASITIC DRAIN	2004-07-02
02-06-03-011	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
02-06-04-015	INTERMITTENT NO CRANK, NO START	2006-03-01
02-06-04-015A	INTERMITTENT NO CRANK, NO START	2006-03-01
02-06-05-004	MISFIRE DTCS P0300, P1380, P1381 AND CATALYTIC CONVERTER DAMAGE DUE TO INSTALLATION OF ALARM SYSTEMS	2006-02-14
02-06-05-004A	MISFIRE DTCS P0300, P1380, P1381 AND CATALYTIC CONVERTER DAMAGE DUE TO INSTALLATION OF ALARM SYSTEMS	2006-02-14
02-06-05-004B	MISFIRE DTCS P0300, P1380, P1381 AND CATALYTIC CONVERTER DAMAGE DUE TO INSTALLATION OF ALARM SYSTEMS	2006-02-14
02-07-30-001	DIAGNOSTIC INFORMATION ON DIAGNOSTIC TROUBLE CODE (DTC) P0894 AND P1870	2005-12-02
02-07-30-001A	DIAGNOSTIC INFORMATION ON DIAGNOSTIC TROUBLE CODE (DTC) P0894 AND P1870	2005-12-02
02-07-30-001B	DIAGNOSTIC INFORMATION ON DIAGNOSTIC TROUBLE CODE (DTC) P0894 AND P1870	2005-12-02
02-07-30-001C	DIAGNOSTIC INFORMATION ON DIAGNOSTIC TROUBLE CODE (DTC) P0894 AND P1870	2005-12-02
02-07-30-001D	DIAGNOSTIC INFORMATION ON DIAGNOSTIC TROUBLE CODE (DTC) P0894 AND P1870	2005-12-02
02-07-30-024	DIAGNOSIS OF CRACKED OR BROKEN TRANSMISSION CASE	2005-08-18
02-07-30-024A	DIAGNOSIS OF CRACKED OR BROKEN TRANSMISSION CASE	2005-08-18
02-07-30-024B	DIAGNOSIS OF CRACKED OR BROKEN TRANSMISSION CASE	2005-08-18
02-07-30-029	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-029A	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-029B	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-029C	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-029D	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-029E	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-029F	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-029G	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
02-07-30-052	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
02-07-30-052A	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
02-07-30-052B	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
02-07-30-052C	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
02-07-30-052D	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
02-08-42-001	INFO - CHEMICAL DAMAGE TO EXTERIOR POLYCARBONATE HEADLAMP LENSES	2004-10-08
	INFO - CHEMICAL DAMAGE TO EXTERIOR POLYCARBONATE	

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 7

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

02-08-42-001A	HEADLAMP LENSES	2004-10-08
02-08-42-001B	INFO - CHEMICAL DAMAGE TO EXTERIOR POLYCARBONATE HEADLAMP LENSES	2004-10-08
02-08-44-007	NEGATIVE IMPACT OF DEALER-INSTALLED CLOTH/VINYL ROOFS ON XM RADIO AND/OR ONSTAR SYSTEMS	2005-12-09
02-08-44-007A	NEGATIVE IMPACT OF DEALER-INSTALLED CLOTH/VINYL ROOFS ON XM RADIO AND/OR ONSTAR SYSTEMS	2005-12-09
02-08-44-007B	NEGATIVE IMPACT OF DEALER-INSTALLED CLOTH/VINYL ROOFS ON XM RADIO AND/OR ONSTAR SYSTEMS	2005-12-09
02-08-46-006	INCORRECT ONSTAR GLOBAL POSITIONING SYSTEM (GPS) LOCATION REPORTED DURING ONSTAR CALL	2005-03-17
02-08-46-006A	INCORRECT ONSTAR GLOBAL POSITIONING SYSTEM (GPS) LOCATION REPORTED DURING ONSTAR CALL	2005-03-17
02-08-46-007	ONSTAR CALL CENTER UNABLE TO REPLENISH CUSTOMERS HANDS-FREE CALLING MINUTES AND OTHER GPS CONCERNS	2005-11-30
02-08-46-007A	ONSTAR CALL CENTER UNABLE TO REPLENISH CUSTOMERS HANDS-FREE CALLING MINUTES AND OTHER GPS CONCERNS	2005-11-30
02-08-46-010	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-46-010A	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-46-010B	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-46-010C	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-46-010D	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-46-010E	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-46-010F	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-46-010G	PROGRAMMING ONSTAR MODULE FOR CANADIAN FRENCH VOICE RECOGNITION (ONSTAR GENERATION 5 OR GENERATION 6)	2006-03-01
02-08-48-001	URETHANE ADHESIVES FOR STATIONARY GLASS AND OTHER APPLICATIONS	2003-12-02
02-08-48-001A	URETHANE ADHESIVES FOR STATIONARY GLASS AND OTHER APPLICATIONS	2003-12-02
02-08-67-009	SUNROOF JAMS WHEN CLOSING (INSTALL GUIDES)	2005-05-16
02-08-67-009A	SUNROOF JAMS WHEN CLOSING (INSTALL GUIDES)	2005-05-16
02-08-98-001	METAL PANEL BONDING	2006-10-09
02-08-98-001A	METAL PANEL BONDING	2006-10-09
02-08-98-001B	METAL PANEL BONDING	2006-10-09
02-08-98-001C	METAL PANEL BONDING	2006-10-09
02-08-98-002	HEM FLANGE REPAIR	2004-10-11
02-08-98-002A	HEM FLANGE REPAIR	2004-10-11
02-09-41-002	AIR BAG LAMP ON, PASSENGER AIR BAG INDICATOR ALWAYS READS OFF, DTC B0092 SET (REPAIR PASSENGER PRESENCE SYSTEM (PPS) SENSOR HARNESS)	2004-03-24
02-09-41-002A	AIR BAG LAMP ON, PASSENGER AIR BAG INDICATOR ALWAYS READS OFF, DTC B0092 SET (REPAIR PASSENGER PRESENCE	2004-03-24

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 8

© 2005 Mitchell Repair Information Company, LLC.



## 2004 Chevrolet Tahoe

All TSBs

SYSTEM (PPS) SENSOR HARNESS)		
02-20-89-014	NEW LABOR OPERATION CODES FOR DEALER-INSTALLED GM ACCESSORIES REPLACED DURING WARRANTY COVERAGE PERIOD	2006-09-07
03-00-89-006C	NEW VEHICLE PRE-DELIVERY INSPECTION (PDI) - DELIVERING QUALITY VEHICLES AND GENERATING HIGHER CSI SCORES	2006-09-22
03-00-89-006D	NEW VEHICLE PRE-DELIVERY INSPECTION (PDI) - DELIVERING QUALITY VEHICLES AND GENERATING HIGHER CSI SCORES	2006-09-22
03-00-89-008	CORROSION PROTECTION FOR METAL PANELS WITH DEALER INSTALLED ACCESSORIES FASTENED BY DRILLED HOLES	2004-01-01
03-00-89-008A	CORROSION PROTECTION FOR METAL PANELS WITH DEALER INSTALLED ACCESSORIES FASTENED BY DRILLED HOLES	2004-01-01
03-00-89-008B	CORROSION PROTECTION FOR METAL PANELS WITH DEALER INSTALLED ACCESSORIES FASTENED BY DRILLED HOLES	2004-01-01
03-00-89-021	NEW VEHICLE PRE-DELIVERY INSPECTION - PERCEIVED FUEL ECONOMY AND DRIVER INFORMATION CENTER CENTER/SAAB INFORMATION DISPLAY (DIC/SID) SETTINGS	2005-10-04
03-00-89-021A	NEW VEHICLE PRE-DELIVERY INSPECTION - PERCEIVED FUEL ECONOMY AND DRIVER INFORMATION CENTER CENTER/SAAB INFORMATION DISPLAY (DIC/SID) SETTINGS	2005-10-04
03-00-91-001	VIBRATION ANALYSIS WORKSHEET	2004-08-09
03-00-91-001A	VIBRATION ANALYSIS WORKSHEET	2004-08-09
03-00-91-001B	VIBRATION ANALYSIS WORKSHEET	2004-08-09
03-01-38-015	HVAC BLOWER MOTOR MAY RUN CONTINUOUSLY AFTER VEHICLE IS TURNED OFF	2003-09-01
03-01-38-019	UNDERHOOD RATTLE NOISE HEARD ON ACCELERATION (CHECK A/C SYSTEM PERFORMANCE AND COMPRESSOR OPERATION)	2004-09-03
03-01-38-019A	UNDERHOOD RATTLE NOISE HEARD ON ACCELERATION (CHECK A/C SYSTEM PERFORMANCE AND COMPRESSOR OPERATION)	2004-09-03
03-01-39-008	CHANGES IN A/C ON/OFF DISPLAY AND SYNCHRONIZING DRIVER/PASSENGER SET TEMPS	2003-06-01
03-02-34-001	INNER TIE ROD RELEASED FOR SERVICE	2003-10-01
03-02-34-001A	INNER TIE ROD RELEASED FOR SERVICE	2003-10-01
03-03-08-002	RATTLE/SQUEAK FROM FRONT OF VEHICLE (REPLACE LOWER PORTION OF UPPER INSULATOR ASSEMBLY)	2005-11-30
03-03-08-002A	RATTLE/SQUEAK FROM FRONT OF VEHICLE (REPLACE LOWER PORTION OF UPPER INSULATOR ASSEMBLY)	2005-11-30
03-03-08-002B	RATTLE/SQUEAK FROM FRONT OF VEHICLE (REPLACE LOWER PORTION OF UPPER INSULATOR ASSEMBLY)	2005-11-30
03-03-10-001	TIRE SLOWLY GOES FLAT AND/OR EXCESSIVE WHEEL VIBRATION CAUSED BY BEAD SPLITS	2006-08-28
03-03-10-001A	TIRE SLOWLY GOES FLAT AND/OR EXCESSIVE WHEEL VIBRATION CAUSED BY BEAD SPLITS	2006-08-28
03-03-10-001B	TIRE SLOWLY GOES FLAT AND/OR EXCESSIVE WHEEL VIBRATION CAUSED BY BEAD SPLITS	2006-08-28
03-03-10-001C	TIRE SLOWLY GOES FLAT AND/OR EXCESSIVE WHEEL VIBRATION CAUSED BY BEAD SPLITS	2006-08-28
03-03-10-002	USE OF CORRECT INSTALLATION PROCEDURE FOR LOOSE HUBCAP ASSEMBLY	2005-11-02
03-03-10-002A	USE OF CORRECT INSTALLATION PROCEDURE FOR LOOSE HUBCAP ASSEMBLY	2005-11-02
03-03-10-002B	USE OF CORRECT INSTALLATION PROCEDURE FOR LOOSE HUBCAP ASSEMBLY	2005-11-02
03-03-10-007	INFO - TIRE CHARACTERISTICS OF GM ORIGINAL EQUIPMENT TIRES	2006-08-17
03-03-10-007A	INFO - TIRE CHARACTERISTICS OF GM ORIGINAL EQUIPMENT	2006-08-17

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 9

© 2005 Mitchell Repair Information Company, LLC.

# 2004 Chevrolet Tahoe

All TSBs

TIRES		
03-03-10-007B	INFO - TIRE CHARACTERISTICS OF GM ORIGINAL EQUIPMENT TIRES	2006-08-17
03-03-16-001	DIAGNOSTIC INFORMATION FOR TIRE PRESSURE MONITORING (TPM) SYSTEM - DTC C0760 AND/OR C0765	2003-10-01
03-04-19-004	GROWL OR MOAN NOISE COMING FROM FRONT AXLE (REPLACE FRONT AXLE DIFFERENTIAL CASE)	2005-12-12
03-04-19-004A	GROWL OR MOAN NOISE COMING FROM FRONT AXLE (REPLACE FRONT AXLE DIFFERENTIAL CASE)	2005-12-12
03-04-19-004B	GROWL OR MOAN NOISE COMING FROM FRONT AXLE (REPLACE FRONT AXLE DIFFERENTIAL CASE)	2005-12-12
03-04-21-006	INOPERATIVE 4WD/AWD LAMPS, INOPERATIVE 4WD/AWD SYSTEM, DTC C0550 SET, NO COMMUNICATION WITH TCCM	2006-07-20
03-05-25-005	SERVICE STABILITY MESSAGE AND DTCS C0455 OR C0550 SET	2003-08-01
03-05-25-007	ANTILOCK BRAKE (ABS) ACTIVATION AT LOW SPEEDS (CLEAN WHEEL SPEED SENSOR MOUNTING SURFACE)	2006-05-16
03-05-25-007A	ANTILOCK BRAKE (ABS) ACTIVATION AT LOW SPEEDS (CLEAN WHEEL SPEED SENSOR MOUNTING SURFACE)	2006-05-16
03-05-25-007B	ANTILOCK BRAKE (ABS) ACTIVATION AT LOW SPEEDS (CLEAN WHEEL SPEED SENSOR MOUNTING SURFACE)	2006-05-16
03-05-25-007C	ANTILOCK BRAKE (ABS) ACTIVATION AT LOW SPEEDS (CLEAN WHEEL SPEED SENSOR MOUNTING SURFACE)	2006-05-16
03-06-03-001	INFO - STARTER CRANKS AFTER KEY IS RELEASED (NORMAL CONDITION)	2006-08-18
03-06-03-001A	INFO - STARTER CRANKS AFTER KEY IS RELEASED (NORMAL CONDITION)	2006-08-18
03-06-03-001B	INFO - STARTER CRANKS AFTER KEY IS RELEASED (NORMAL CONDITION)	2006-08-18
03-06-03-001C	INFO - STARTER CRANKS AFTER KEY IS RELEASED (NORMAL CONDITION)	2006-08-18
03-06-03-004	MIDTRONICS CODE GENERATED BY J-42000 OR J-42000EU BATTERY TESTER REQUIRED FOR CLAIM PROCESSING ON LABOR OPERATION N0110	2004-11-10
03-06-03-004A	MIDTRONICS CODE GENERATED BY J-42000 OR J-42000EU BATTERY TESTER REQUIRED FOR CLAIM PROCESSING ON LABOR OPERATION N0110	2004-11-10
03-06-03-006	INTERMITTENT NO CRANK, NO START	2006-03-01
03-06-03-006A	INTERMITTENT NO CRANK, NO START	2006-03-01
03-06-04-012	INSPECTION OF RELATED WIRING HARNESS CONNECTIONS WHEN DIAGNOSING MISC. DTCS, INTERMITTENT DRIVEABILITY CONCERNS, HARD START, NO START, INCORRECT GAUGES, INOP I/C SYSTEMS, SES/4WD LAMPS ILLUMINATED	2005-08-10
03-06-04-012A	INSPECTION OF RELATED WIRING HARNESS CONNECTIONS WHEN DIAGNOSING MISC. DTCS, INTERMITTENT DRIVEABILITY CONCERNS, HARD START, NO START, INCORRECT GAUGES, INOP I/C SYSTEMS, SES/4WD LAMPS ILLUMINATED	2005-08-10
03-06-04-030	MULTIPLE DRIVEABILITY SYMPTOMS DUE TO CLOGGED FUEL INJECTORS (CLEAN INJECTORS)	2004-06-24
03-06-04-030A	MULTIPLE DRIVEABILITY SYMPTOMS DUE TO CLOGGED FUEL INJECTORS (CLEAN INJECTORS)	2004-06-24
03-06-04-060	INFORMATION ON NEW SPARK PLUGS AND GAPPING	2003-10-24
03-06-05-008	POPPING/SNAPPING NOISE WHEN VEHICLE IS HOT, AT IDLE, OR IMMEDIATELY AFTER VEHICLE IS SHUT OFF (REPLACE MUFFLER HEAT SHIELD)	2005-10-28
03-06-05-008A	POPPING/SNAPPING NOISE WHEN VEHICLE IS HOT, AT IDLE, OR IMMEDIATELY AFTER VEHICLE IS SHUT OFF (REPLACE MUFFLER HEAT SHIELD)	2005-10-28
03-06-05-008B	POPPING/SNAPPING NOISE WHEN VEHICLE IS HOT, AT IDLE, OR IMMEDIATELY AFTER VEHICLE IS SHUT OFF (REPLACE	2005-10-28

XXX

## 2004 Chevrolet Tahoe

All TSBs

	MUFFLER HEAT SHIELD)	
03-06-05-008C	POPPING/SNAPPING NOISE WHEN VEHICLE IS HOT, AT IDLE, OR IMMEDIATELY AFTER VEHICLE IS SHUT OFF (REPLACE MUFFLER HEAT SHIELD)	2005-10-28
03-07-30-002	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
03-07-30-002A	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
03-07-30-002B	AUTOMATIC TRANSMISSION OIL COOLER FLUSH AND FLOW TEST ESSENTIAL TOOL J-45096 TRANSFLOW	2006-02-06
03-07-30-007	ENGAGEMENT TIME OF ELECTRONICALLY CONTROLLED TRANSMISSIONS IN GENERAL MOTORS VEHICLES (GARAGE SHIFTS, PARK TO REVERSE, NEUTRAL TO DRIVE, NEUTRAL TO REVERSE, PARK TO DRIVE, DELAYED ENGAGEMENT)	2005-08-02
03-07-30-007A	ENGAGEMENT TIME OF ELECTRONICALLY CONTROLLED TRANSMISSIONS IN GENERAL MOTORS VEHICLES (GARAGE SHIFTS, PARK TO REVERSE, NEUTRAL TO DRIVE, NEUTRAL TO REVERSE, PARK TO DRIVE, DELAYED ENGAGEMENT)	2005-08-02
03-07-30-007B	ENGAGEMENT TIME OF ELECTRONICALLY CONTROLLED TRANSMISSIONS IN GENERAL MOTORS VEHICLES (GARAGE SHIFTS, PARK TO REVERSE, NEUTRAL TO DRIVE, NEUTRAL TO REVERSE, PARK TO DRIVE, DELAYED ENGAGEMENT)	2005-08-02
03-07-30-027	MOST FREQUENTLY ASKED QUESTIONS AND ANSWERS FOR J 45096 TRANSFLOW TRANSMISSION OIL COOLING SYSTEM FLUSHING MACHINE	2003-06-25
03-07-30-043	INFORMATION REGARDING AUTOMATIC TRANSMISSION SHIFT LOCK CONTROL FUNCTION	2006-05-25
03-07-30-043A	INFORMATION REGARDING AUTOMATIC TRANSMISSION SHIFT LOCK CONTROL FUNCTION	2006-05-25
03-07-30-056	4L60-E AUTOMATIC TRANSMISSION OIL PUMP FIRST AND SECOND DESIGN IDENTIFICATION	2003-11-05
03-08-43-002	REAR WINDOW WASHER SPRAY NOZZLE DRIPS LEAVING STAIN ON REAR BUMPER STEP COVER	2004-09-10
03-08-43-002A	REAR WINDOW WASHER SPRAY NOZZLE DRIPS LEAVING STAIN ON REAR BUMPER STEP COVER	2004-09-10
03-08-44-001	XM RADIO LABOR OPERATION CODES	2005-04-26
03-08-44-001A	XM RADIO LABOR OPERATION CODES	2005-04-26
03-08-44-018	REAR SEAT AUDIO (RSA) AND/OR REAR HVAC INOPERATIVE (REPLACE RSA MODULE)	2006-01-09
03-08-44-018A	REAR SEAT AUDIO (RSA) AND/OR REAR HVAC INOPERATIVE (REPLACE RSA MODULE)	2006-01-09
03-08-44-018B	REAR SEAT AUDIO (RSA) AND/OR REAR HVAC INOPERATIVE (REPLACE RSA MODULE)	2006-01-09
03-08-44-018C	REAR SEAT AUDIO (RSA) AND/OR REAR HVAC INOPERATIVE (REPLACE RSA MODULE)	2006-01-09
03-08-44-022	PARTS RESTRICTION ON ORDERING XM DIGITAL RADIO RECEIVER	2006-03-20
03-08-44-022A	PARTS RESTRICTION ON ORDERING XM DIGITAL RADIO RECEIVER	2006-03-20
03-08-44-022B	PARTS RESTRICTION ON ORDERING XM DIGITAL RADIO RECEIVER	2006-03-20
03-08-44-022C	PARTS RESTRICTION ON ORDERING XM DIGITAL RADIO RECEIVER	2006-03-20
03-08-46-004	PARTS RESTRICTION ON ORDERING ONSTAR GENERATION 5 AND 6 VEHICLE COMMUNICATION INTERFACE MODULES (VCIM)	2005-11-16
03-08-46-004A	PARTS RESTRICTION ON ORDERING ONSTAR GENERATION 5 AND 6 VEHICLE COMMUNICATION INTERFACE MODULES (VCIM)	2005-11-16
03-08-46-004B	PARTS RESTRICTION ON ORDERING ONSTAR GENERATION 5, 6 AND 7 VEHICLE COMMUNICATION INTERFACE MODULES (VCIM)	2006-04-18

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 11

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

03-08-46-004C	PARTS RESTRICTION ON ORDERING ONSTAR GENERATION 5, 6 AND 7 VEHICLE COMMUNICATION INTERFACE MODULES (VCIM)	2006-04-18
03-08-48-005	COMPASS ZONE ADJUSTMENT AND CALIBRATION PROCEDURE DURING PRE-DELIVERY INSPECTION	2005-03-10
03-08-48-005A	COMPASS ZONE ADJUSTMENT AND CALIBRATION PROCEDURE DURING PRE-DELIVERY INSPECTION	2005-03-10
03-08-48-005B	COMPASS ZONE ADJUSTMENT AND CALIBRATION PROCEDURE DURING PRE-DELIVERY INSPECTION	2005-03-10
03-08-48-006	REPAIR INFORMATION FOR RECONNECTION OF REAR WINDOW DEFROSTER CONTACT OR TAB	2003-09-29
03-08-50-014A	NO COMMUNICATION WITH ANY MODULES, MEMORY SEAT MAY NOT RECALL, MULTIPLE U-DTCS SET OR INSTRUMENT PANEL CLUSTER (IPC) WARNING INDICATORS, CRANK NO START (INSPECT/REPAIR AFFECTED WIRING HARNESS)	2006-01-20
03-08-52-005	DIAGNOSTIC INFO FOR RKE TRANSMITTER INOPERATIVE - UNABLE TO SYNCHRONIZE	2003-09-16
03-08-61-002	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-61-002A	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-61-002B	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-61-002C	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-61-002D	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-61-002E	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-61-002F	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-61-002G	SNAP/POPPING TYPE NOISE COMING FROM FRONT OF VEHICLE (REMOVE BOLT-IN FRONT CROSSMEMBER AND ADD WASHERS)	2006-02-14
03-08-64-010	OUTSIDE REARVIEW MIRRORS MAY BLOW IN AT HIGHWAY SPEEDS OR POWER FOLDING FEATURE APPEARS INOPERATIVE (SYNCHRONIZE MIRRORS)	2006-02-22
03-08-64-010A	OUTSIDE REARVIEW MIRRORS MAY BLOW IN AT HIGHWAY SPEEDS OR POWER FOLDING FEATURE APPEARS INOPERATIVE (SYNCHRONIZE MIRRORS)	2006-02-22
03-08-64-010B	OUTSIDE REARVIEW MIRRORS MAY BLOW IN AT HIGHWAY SPEEDS OR POWER FOLDING FEATURE APPEARS INOPERATIVE (SYNCHRONIZE MIRRORS)	2006-02-22
03-08-64-022	REMOVING FRONT DOOR TRIM PANEL DURING SWITCH REMOVAL	2003-07-22
03-08-64-029	REMOVING FRONT DOOR TRIM PANEL TO AVOID BREAKAGE	2003-08-26
03-08-64-037	DIAGNOSTIC INFORMATION FOR FRONT POWER WINDOW NOISY OR INOPERATIVE	2004-06-15
03-08-64-037A	DIAGNOSTIC INFORMATION FOR FRONT POWER WINDOW NOISY OR INOPERATIVE	2004-06-15
03-08-64-037B	DIAGNOSTIC INFORMATION FOR FRONT POWER WINDOW NOISY OR INOPERATIVE	2004-06-15
03-08-98-002	SQUEEZE TYPE RESISTANCE SPOT WELDING/EQUIPMENT	2004-10-11

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 12

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

03-08-98-002A	SQUEEZE TYPE RESISTANCE SPOT WELDING/EQUIPMENT	2004-10-11
03-09-41-003	PROPER AIR BAG SYSTEM DIAGNOSIS AND SERVICE	2005-02-09
03-09-41-003A	PROPER AIR BAG SYSTEM DIAGNOSIS AND SERVICE	2005-02-09
04004A	F/CMVSS NONCOMPLIANCE - BRAKE HYDRO-BOOST RELIEF VALVE SEAL FRACTURE	2004-06-18
04-00-89-011	PART AND ACCESSORY REPLACEMENT POLICY	2004-03-29
04-01-37-001	HVAC CONTROL KNOB REPLACEMENT	2004-01-01
04-01-37-004	SMU - REVISED AIR CONDITIONING (A/C) SYSTEM PERFORMANCE TEST	2004-04-20
04-01-38-008	HVAC SYSTEM CANNOT BE CONTROLLED OR DEFAULTS TO DEFROST MODE (REPAIR HVAC ACTUATOR HARNESS)	2004-06-17
04-01-38-010	DIAGNOSTIC INFORMATION TO ACCURATELY DIAGNOSE A/C LOW PRESSURE SWITCH USING NEW KENT MOORE SPECIAL TOOL GE-47742	2004-08-05
04-01-38-013	HVAC NOT COLD ENOUGH, A/C COMPRESSOR DOES NOT ENGAGE (REPAIR ENGINE COMPARTMENT WIRING HARNESS NEAR IDLER ARM)	2004-10-08
04-01-38-014	ADVANCED SERVICE INFO - HIGH PITCHED TONE HEARD INSIDE VEHICLE WHEN A/C COMPRESSOR IS ENGAGED (FIX NOT AVAILABLE YET)	2004-10-08
04-01-38-015	DIAGNOSTIC INFORMATION FOR MOAN, GROAN OR BOOM NOISE AT IDLE, VIBRATION IN STEERING WHEEL OR FELT THROUGH FLOOR WHEN A/C COMPRESSOR ENGAGES - DO NOT REPLACE A/C COMPRESSOR	2004-10-08
04-01-38-018	HVAC MODULE EXTERNAL SEAL KIT NOW AVAILABLE FOR SERVICE USE	2004-11-30
04-01-39-009	HVAC BLOWER MOTOR INOPERATIVE OR STAYS RUNNING (REPLACE BLOWER MOTOR CONTROL MODULE)	2004-12-16
04-01-39-009A	HVAC BLOWER MOTOR INOPERATIVE OR STAYS RUNNING (REPLACE BLOWER MOTOR CONTROL MODULE)	2004-12-16
04-01-39-009B	HVAC BLOWER MOTOR INOPERATIVE OR STAYS RUNNING (REPLACE BLOWER MOTOR CONTROL MODULE)	2004-12-16
04-02-34-001	VEHICLE PULLS ON BRAKING, ACCELERATION AND WANDERS (PERFORM DIAGNOSTIC CHECKS)	2004-10-04
04-03-07-002	NEW ALIGNMENT PROCEDURE FOR LABOR OPERATION NUMBERS E2020 AND E2000	2004-11-10
04-03-07-002A	NEW ALIGNMENT PROCEDURE FOR LABOR OPERATION NUMBERS E2020 AND E2000	2004-11-10
04-03-10-001	TIRE PUNCTURE REPAIR PROCEDURES FOR ALL CARS AND LIGHT DUTY TRUCKS	2006-10-02
04-03-10-001A	TIRE PUNCTURE REPAIR PROCEDURES FOR ALL CARS AND LIGHT DUTY TRUCKS	2006-10-02
04-03-10-001B	TIRE PUNCTURE REPAIR PROCEDURES FOR ALL CARS AND LIGHT DUTY TRUCKS	2006-10-02
04-03-10-001C	TIRE PUNCTURE REPAIR PROCEDURES FOR ALL CARS AND LIGHT DUTY TRUCKS	2006-10-02
04-03-10-005	SPARE TIRE DOES NOT FIT ON HOIST (REPLACE HOIST ASSEMBLY)	2004-07-23
04-03-10-007	20 INCH WHEELS AND TIRES AVAILABLE THROUGH GM ACCESSORIES	2005-11-17
04-03-10-007A	20 INCH WHEELS AND TIRES AVAILABLE THROUGH GM ACCESSORIES	2005-11-17
04-03-10-007B	20 INCH WHEELS AND TIRES AVAILABLE THROUGH GM ACCESSORIES	2005-11-17
04-03-10-007C	20 INCH WHEELS AND TIRES AVAILABLE THROUGH GM ACCESSORIES	2005-11-17
04-03-10-007D	20 INCH WHEELS AND TIRES AVAILABLE THROUGH GM ACCESSORIES	2005-11-17

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 13

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

04-03-10-007E	20 INCH WHEELS AND TIRES AVAILABLE THROUGH GM ACCESSORIES	2005-11-17
04-03-10-012	PITTING AND BRAKE DUST ON CHROME WHEELS	2006-09-22
04-03-10-012A	PITTING AND BRAKE DUST ON CHROME WHEELS	2006-09-22
04-03-16-002	TIRE PRESSURE MONITORING SYSTEM DESCRIPTION, OPERATION AND DIAGNOSTICS	2004-04-07
04-03-16-003	TIRE SLOWLY LOSES AIR, LOW TIRE PRESSURE WARNING LIGHT ON, CHECK TIRE PRESSURE MESSAGE DISPLAYED (REPLACE TIRE PRESSURE SENSOR GROMMET)	2004-11-30
04-04-21-003	AUTOMATIC TRANSFER CASE CLUTCH PLATE SHIMMING - PARTS AVAILABILITY CHANGE	2004-11-10
04-05-23-006	REVISED BRAKE PADS REPLACEMENT-REAR	2004-08-02
04-05-25-002	ABS LIGHT ON, DTCS C0265, C0201, U1041 SET AND/OR LOSS OF COMMUNICATION WITH BRAKE MODULE	2004-04-22
04-05-25-002	ABS LIGHT ON, DTCS C0265, C0201, U1041 SET AND/OR LOSS OF COMMUNICATION WITH BRAKE MODULE (REGROUND EBCM GROUND)	2005-11-23
04-05-25-002A	ABS LIGHT ON, DTCS C0265, C0201, U1041 SET AND/OR LOSS OF COMMUNICATION WITH BRAKE MODULE	2004-04-22
04-05-25-002A	ABS LIGHT ON, DTCS C0265, C0201, U1041 SET AND/OR LOSS OF COMMUNICATION WITH BRAKE MODULE (REGROUND EBCM GROUND)	2005-11-23
04-05-25-002B	ABS LIGHT ON, DTCS C0265, C0201, U1041 SET AND/OR LOSS OF COMMUNICATION WITH BRAKE MODULE (REGROUND EBCM GROUND)	2005-11-23
04-05-25-002C	ABS LIGHT ON, DTCS C0265, C0201, U1041 SET AND/OR LOSS OF COMMUNICATION WITH BRAKE MODULE (REGROUND EBCM GROUND)	2005-11-23
04-06-01-019	GM PERFORMANCE PARTS ENGINE WARRANTY QUESTIONS AND ANSWERS	2004-06-14
04-06-01-023	ENGINE VIBRATION/NOISE AT IDLE, ROUGH IDLE, STEERING WHEEL SHAKE (ADJUST ENGINE MOUNT BRACKET(S))	2004-06-30
04-06-01-029	UNNECESSARY ENGINE CRANKCASE AND SUBSYSTEMS FLUSHING SERVICES, ADDITIVE RECOMMENDATIONS AND PROPER UTILIZATION OF GM SIMPLIFIED MAINTENANCE SCHEDULE TO ENHANCE CUSTOMER SERVICE EXPERIENCE	2004-10-11
04-06-01-034	INSTRUCTIONS TO BE FOLLOWED TO AID IN OBTAINING ROOT CAUSE ANALYSIS ON BOTH OEM AND GOODWRENCH ENGINES, TRANSMISSIONS AND TRANSFER CASES ON VEHICLES WITH 402 KM (250 MI) OR LESS	2006-05-17
04-06-01-034A	INSTRUCTIONS TO BE FOLLOWED TO AID IN OBTAINING ROOT CAUSE ANALYSIS ON BOTH OEM AND GOODWRENCH ENGINES, TRANSMISSIONS AND TRANSFER CASES ON VEHICLES WITH 402 KM (250 MI) OR LESS	2006-05-17
04-06-01-034B	INSTRUCTIONS TO BE FOLLOWED TO AID IN OBTAINING ROOT CAUSE ANALYSIS ON BOTH OEM AND GOODWRENCH ENGINES, TRANSMISSIONS AND TRANSFER CASES ON VEHICLES WITH 402 KM (250 MI) OR LESS	2006-05-17
04-06-01-034C	INSTRUCTIONS TO BE FOLLOWED TO AID IN OBTAINING ROOT CAUSE ANALYSIS ON BOTH OEM AND GOODWRENCH ENGINES, TRANSMISSIONS AND TRANSFER CASES ON VEHICLES WITH 402 KM (250 MI) OR LESS	2006-05-17
04-06-03-001	INCORRECT AMP CODE ON GENERATOR	2004-02-03
04-06-03-002	DIAGNOSTIC INFORMATION FOR INTERMITTENT VEHICLE NO CRANK/DEAD BATTERY	2005-11-16
04-06-03-016	BATTERY SPECIFICATION LABEL	2004-12-13
04-06-04-012	VEHICLE WITH FLEXIBLE FUEL (RPO L59) WILL NOT START, STALLS AND WILL NOT RESTART, LOSS OF POWER, POOR PERFORMANCE AND/OR FUEL GAUGE READS INACCURATE/INCORRECT (REPLACE FUEL SENDER/MODULE	2004-12-06

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 14

© 2005 Mitchell Repair Information Company, LLC.

# 2004 Chevrolet Tahoe

All TSBs

ASSEMBLY)		
04-06-04-012A	VEHICLE WITH FLEXIBLE FUEL (RPO L59) WILL NOT START, STALLS AND WILL NOT RESTART, LOSS OF POWER, POOR PERFORMANCE AND/OR FUEL GAUGE READS INACCURATE/INCORRECT (REPLACE FUEL SENDER/MODULE ASSEMBLY)	2004-12-06
04-06-04-012B	VEHICLE WITH FLEXIBLE FUEL (RPO L59) WILL NOT START, STALLS AND WILL NOT RESTART, LOSS OF POWER, POOR PERFORMANCE AND/OR FUEL GAUGE READS INACCURATE/INCORRECT (REPLACE FUEL SENDER/MODULE ASSEMBLY)	2004-12-06
04-06-04-032	PROPER METHOD TO SECURE FUEL CAP DURING REFUELING	2004-04-28
04-06-04-036	WARRANTY COVERAGE CHANGE FOR EMISSION-RELATED REPROGRAMMING EVENTS (PCM, ECM AND TCM)	2004-05-20
04-06-04-036A	WARRANTY COVERAGE FOR EMISSION-RELATED REPROGRAMMING EVENTS, (PCM, ECM AND TCM)	2006-05-12
04-06-04-036B	WARRANTY COVERAGE FOR EMISSION-RELATED REPROGRAMMING EVENTS, (PCM, ECM AND TCM)	2006-05-12
04-06-04-043	UNABLE TO RESET ENGINE OIL LIFE MONITOR (REPROGRAM PCM)	2004-06-17
04-06-04-045	INFO - OIL LIFE MONITORING SYSTEM - PCM RESET	2004-06-22
04-06-04-047	TOP TIER DETERGENT GASOLINE (DEPOSITS, FUEL ECONOMY, NO START, POWER, PERFORMANCE, STALL CONCERNS)	2006-07-21
04-06-04-047A	TOP TIER DETERGENT GASOLINE (DEPOSITS, FUEL ECONOMY, NO START, POWER, PERFORMANCE, STALL CONCERNS)	2006-07-21
04-06-04-047B	TOP TIER DETERGENT GASOLINE (DEPOSITS, FUEL ECONOMY, NO START, POWER, PERFORMANCE, STALL CONCERNS)	2006-07-21
04-06-04-047C	TOP TIER DETERGENT GASOLINE (DEPOSITS, FUEL ECONOMY, NO START, POWER, PERFORMANCE, STALL CONCERNS)	2006-07-21
04-06-04-047D	TOP TIER DETERGENT GASOLINE (DEPOSITS, FUEL ECONOMY, NO START, POWER, PERFORMANCE, STALL CONCERNS)	2006-07-21
04-06-04-047E	TOP TIER DETERGENT GASOLINE (DEPOSITS, FUEL ECONOMY, NO START, POWER, PERFORMANCE, STALL CONCERNS)	2006-07-21
04-06-04-047F	TOP TIER DETERGENT GASOLINE (DEPOSITS, FUEL ECONOMY, NO START, POWER, PERFORMANCE, STALL CONCERNS)	2006-07-21
04-06-04-051	MAINTENANCE CLEANING OF FUEL INJECTORS	2006-01-04
04-06-04-051A	MAINTENANCE CLEANING OF FUEL INJECTORS	2006-01-04
04-06-04-051B	MAINTENANCE CLEANING OF FUEL INJECTORS	2006-01-04
04-06-04-054	NON-GM PARTS AND ACCESSORIES (AFTERMARKET)	2004-07-28
04-06-04-065A	HIGH, LOW OR ERRATIC OIL PRESSURE GAUGE READING SETTING DTCS P0522 AND/OR P0523	2004-10-20
04-07-30-006	4L65-E, 4L60-E, 4L60 AND 200-4R AUTOMATIC TRANSMISSION OIL PUMP SPRING FIRST AND SECOND DESIGN IDENTIFICATION	2004-02-11
04-07-30-013	AUTOMATIC TRANSMISSION SHIFT, ENGINE DRIVEABILITY CONCERNS OR SERVICE ENGINE SOON (SES) LIGHT ON AS A RESULT OF THE USE OF AN EXCESSIVELY/OVER-OILED AFTERMARKET, REUSABLE AIR FILTER	2005-01-25
04-07-30-013A	AUTOMATIC TRANSMISSION SHIFT, ENGINE DRIVEABILITY CONCERNS OR SERVICE ENGINE SOON (SES) LIGHT ON AS A RESULT OF THE USE OF AN EXCESSIVELY/OVER-OILED AFTERMARKET, REUSABLE AIR FILTER	2005-01-25
04-07-30-023	INFO - OIL PUMP ASSEMBLY SEAL AND TRANSMISSION CASE CHANGE	2004-05-12
04-07-30-025	TRANSMISSION FLUID LEAK, INOPERATIVE 2ND/3RD/4TH GEARS, NO MOVEMENT, CASE CRACKED OR BROKEN AT 2-4 SERVO (REPAIR TRANSMISSION AND INSTALL NEW RETAINING RING)	2004-07-27
	TRANSMISSION FLUID LEAK, INOPERATIVE 2ND/3RD/4TH GEARS, NO MOVEMENT, CASE CRACKED OR BROKEN AT 2-4	

XXX

## 2004 Chevrolet Tahoe

All TSBs

04-07-30-025A	SERVO (REPAIR TRANSMISSION AND INSTALL NEW RETAINING RING)	2004-07-27
04-07-30-037	RELEASE OF DEXRON VI AUTOMATIC TRANSMISSION FLUID (ATF)	2006-06-12
04-07-30-037A	RELEASE OF DEXRON VI AUTOMATIC TRANSMISSION FLUID (ATF)	2006-06-12
04-07-30-037B	RELEASE OF DEXRON VI AUTOMATIC TRANSMISSION FLUID (ATF)	2006-06-12
04-08-111-002A	DIMPLE IN BODY SIDE MOLDING	2006-10-26
04-08-111-002B	DIMPLE IN BODY SIDE MOLDING	2006-10-26
04-08-43-003	REPLACEMENT OF WINDSHIELD WIPER INSERTS	2004-04-14
04-08-44-005	UTILIZING TECH 2 TO RETRIEVE PART NUMBERS FOR RADIOS, COMPACT DISC (CD) CHANGERS AND INSTRUMENT PANEL CLUSTERS (IPC)	2004-03-24
04-08-44-005A	UTILIZING TECH 2 TO RETRIEVE PART NUMBERS FOR RADIOS, COMPACT DISC (CD) CHANGERS AND INSTRUMENT PANEL CLUSTERS (IPC)	2006-06-27
04-08-44-005B	UTILIZING TECH 2 TO RETRIEVE PART NUMBERS FOR RADIOS, COMPACT DISC (CD) CHANGERS AND INSTRUMENT PANEL CLUSTERS (IPC)	2006-06-27
04-08-44-009	PARTS RESTRICTION ON ORDERING XM DIGITAL RADIO RECEIVER	2006-03-20
04-08-44-009A	PARTS RESTRICTION ON ORDERING XM DIGITAL RADIO RECEIVER	2006-03-20
04-08-44-020	CD PLAYER LONG LOAD-TO-PLAY TIME, ERROR MESSAGE, CD DOES NOT RETURN TO PREVIOUS TRACK, CD DOES NOT PLAY, CD DOES NOT EJECT, CD STUCK IN PLAYER, RADIO WILL NOT ACCEPT CD (REPROGRAM RADIO)	2005-11-09
04-08-44-020A	CD PLAYER LONG LOAD-TO-PLAY TIME, ERROR MESSAGE, CD DOES NOT RETURN TO PREVIOUS TRACK, CD DOES NOT PLAY, CD DOES NOT EJECT, CD STUCK IN PLAYER, RADIO WILL NOT ACCEPT CD (REPROGRAM RADIO)	2005-11-09
04-08-44-020B	CD PLAYER LONG LOAD-TO-PLAY TIME, ERROR MESSAGE, CD DOES NOT RETURN TO PREVIOUS TRACK, CD DOES NOT PLAY, CD DOES NOT EJECT, CD STUCK IN PLAYER, RADIO WILL NOT ACCEPT CD (REPROGRAM RADIO)	2005-11-09
04-08-44-020C	CD PLAYER LONG LOAD-TO-PLAY TIME, ERROR MESSAGE, CD DOES NOT RETURN TO PREVIOUS TRACK, CD DOES NOT PLAY, CD DOES NOT EJECT, CD STUCK IN PLAYER, RADIO WILL NOT ACCEPT CD (REPROGRAM RADIO)	2005-11-09
04-08-46-002	RADIO TELEPHONE/MOBILE RADIO (TRANSCIEVER) INSTALLATION AND TROUBLESHOOTING GUIDELINES	2004-10-28
04-08-46-003	INFO (ALASKA ONLY) - UNABLE TO CONNECT TO ONSTAR OR ONSTAR PERSONAL CALLING INOPERATIVE	2006-02-07
04-08-46-003A	INFO (ALASKA ONLY) - UNABLE TO CONNECT TO ONSTAR OR ONSTAR PERSONAL CALLING INOPERATIVE	2006-02-07
04-08-46-003B	INFO (ALASKA ONLY) - UNABLE TO CONNECT TO ONSTAR OR ONSTAR PERSONAL CALLING INOPERATIVE	2006-02-07
04-08-46-005	ONSTAR GENERATION 5 OR 6 (DIGITAL) SYSTEM INOPERATIVE/HAS NO POWER, LED LIGHT NOT ON	2006-10-19
04-08-48-001	REAR WINDOW DEFOGGER - BROKEN HEATING GRID DETECTION METHOD	2005-06-28
04-08-48-001A	REAR WINDOW DEFOGGER - BROKEN HEATING GRID DETECTION METHOD	2005-06-28
04-08-48-001B	REAR WINDOW DEFOGGER - BROKEN HEATING GRID DETECTION METHOD	2005-06-28
04-08-48-003	WINDRUSH AROUND WINDSHIELD (INSTALL NEW WINDSHIELD REVEAL MOLDINGS)	2004-06-14
04-08-49-006	SERVICE STABILITY MESSAGE DISPLAYED, DTC C0550 SET	2005-01-05

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 16

© 2005 Mitchell Repair Information Company, LLC.



## 2004 Chevrolet Tahoe

All TSBs

	(REPROGRAM EBCM)	
04-08-49-006A	SERVICE STABILITY MESSAGE DISPLAYED, DTC C0550 SET (REPROGRAM EBCM)	2005-01-05
04-08-49-006B	SERVICE STABILITY MESSAGE DISPLAYED, DTC C0550 SET (REPROGRAM EBCM)	2005-01-05
04-08-49-006C	SERVICE STABILITY MESSAGE DISPLAYED, DTC C0550 SET (REPROGRAM EBCM)	2005-01-05
04-08-49-007	PERSONAL TRIP/BUSINESS TRIP FEATURE - MUST BE ON FOR TRIP ODOMETER TO ACCUMULATE	2004-02-26
04-08-49-015	NOISE COMING FROM INSTRUMENT PANEL CLUSTER (REPLACE INSTRUMENT PANEL CLUSTER)	2004-04-05
04-08-49-018	CRANKS BUT NO START, STALL, INACCURATE/INCORRECT FUEL GAUGE READING, NO FUEL, VEHICLE IS OUT OF FUEL AND FUEL GAUGE READS ABOVE EMPTY (REPLACE FUEL LEVEL SENSOR)	2005-01-05
04-08-49-018A	CRANKS BUT NO START, STALL, INACCURATE/INCORRECT FUEL GAUGE READING, NO FUEL, VEHICLE IS OUT OF FUEL AND FUEL GAUGE READS ABOVE EMPTY (REPLACE FUEL LEVEL SENSOR)	2005-01-05
04-08-49-018B	CRANKS BUT NO START, STALL, INACCURATE/INCORRECT FUEL GAUGE READING, NO FUEL, VEHICLE IS OUT OF FUEL AND FUEL GAUGE READS ABOVE EMPTY (REPLACE FUEL LEVEL SENSOR)	2005-01-05
04-08-49-018C	CRANKS BUT NO START, STALL, INACCURATE/INCORRECT FUEL GAUGE READING, NO FUEL, VEHICLE IS OUT OF FUEL AND FUEL GAUGE READS ABOVE EMPTY (REPLACE FUEL LEVEL SENSOR)	2005-01-05
04-08-49-018D	CRANKS BUT NO START, STALL, INACCURATE/INCORRECT FUEL GAUGE READING, NO FUEL, VEHICLE IS OUT OF FUEL AND FUEL GAUGE READS ABOVE EMPTY (REPLACE FUEL LEVEL SENSOR)	2005-01-05
04-08-49-018E	CRANKS BUT NO START, STALL, INACCURATE/INCORRECT FUEL GAUGE READING, NO FUEL, VEHICLE IS OUT OF FUEL AND FUEL GAUGE READS ABOVE EMPTY (REPLACE FUEL LEVEL SENSOR)	2005-01-05
04-08-49-026	FUEL GAUGE DOES NOT READ FULL AFTER FILLING TANK (REPROGRAM PCM)	2004-10-20
04-08-50-003	ENABLING MEMORY SEAT FEATURE VIA DIC IF INOPERATIVE	2005-02-26
04-08-50-006	MINOR WRINKLES/CREASES, DISCOLORATION, CIGARETTE BURNS, AND CUSTOMER INDUCED CUTS AND STAINS ON FRONT AND REAR DRIVER AND PASSENGER SEATS WITH LEATHER, VINYL OR CLOTH SEAT COVERS	2006-09-07
04-08-50-006A	MINOR WRINKLES/CREASES, DISCOLORATION, CIGARETTE BURNS, AND CUSTOMER INDUCED CUTS AND STAINS ON FRONT AND REAR DRIVER AND PASSENGER SEATS WITH LEATHER, VINYL OR CLOTH SEAT COVERS	2006-09-07
04-08-50-007	SERVICE INFORMATION FOR FRONT HEATED SEAT INOPERATIVE/COLD	2004-03-12
04-08-50-011	REPAIRING NAPPED SEAT FABRIC	2006-05-04
04-08-50-011A	REPAIRING NAPPED SEAT FABRIC	2006-05-04
04-08-50-016	MEMORY SEAT MAY NOT RETURN TO REQUESTED POSITION (REPROGRAM DRIVER SEAT MODULE)	2005-08-12
04-08-50-016A	MEMORY SEAT MAY NOT RETURN TO REQUESTED POSITION (REPROGRAM DRIVER SEAT MODULE)	2005-08-12
04-08-50-016B	MEMORY SEAT MAY NOT RETURN TO REQUESTED POSITION (REPROGRAM DRIVER SEAT MODULE)	2005-08-12
04-08-50-016C	MEMORY SEAT MAY NOT RETURN TO REQUESTED POSITION (REPROGRAM DRIVER SEAT MODULE)	2005-08-12
04-08-52-005	REMOTE KEYLESS ENTRY (RKE) SYSTEM INOPERATIVE (REPROGRAM PASSENGER DOOR MODULE PDM)	2004-06-15

XXX

## 2004 Chevrolet Tahoe

All TSBs

04-08-64-003	POWER WINDOW MOTOR NOW AVAILABLE SEPARATELY FROM THE POWER WINDOW REGULATOR ASSEMBLY	2004-02-25
04-08-64-003A	POWER WINDOW MOTOR NOW AVAILABLE SEPARATELY FROM THE POWER WINDOW REGULATOR ASSEMBLY	2004-02-25
04-08-64-016	REAR DOOR PUDDLE LAMP REFLECTOR REPLACEMENT	2004-08-09
04-08-68-002	CRUISE CONTROL OPERATION - INCREASING SET SPEED	2004-09-22
04-08-98-001	ADDITIONAL MATERIAL AND SOURCE FOR METAL PANEL BONDING ADHESIVES	2004-05-26
04-08-98-002	REPAIR PROCEDURE FOR SERVICE SHEET METAL, CRATERS IN ELPO SURFACE	2004-08-02
04-09-41-003	PROPER USE OF LABOR OPERATION CODE WHEN DIAGNOSIS LEADS TO SIR PASSENGER PRESENCE SYSTEM REPLACEMENT)	2004-06-22
05-00-89-024	WARRANTY COVERAGE AND PROCEDURES FOR JOE GIBBS PERFORMANCE (JGP) VEHICLES (CORPORATE SERVICE BULLETIN 05-00-89-024)	2005-07-18
05-00-89-045	ELECTRONIC EXCHANGE PROGRAM GOODWILL PROCEDURES	2005-07-22
05-00-89-072	FUEL AND OIL ADDITIVES - FACTS AND MYTHS/MAXIMIZING FUEL ECONOMY	2005-10-24
05-00-89-078	GM FUEL SYSTEM TREATMENT PLUS, FUEL SENDING UNIT CORROSION AND FUEL SYSTEM DEPOSITS	2006-09-14
05-00-89-078A	GM FUEL SYSTEM TREATMENT PLUS, FUEL SENDING UNIT CORROSION AND FUEL SYSTEM DEPOSITS	2006-09-14
05-00-90-010	REVISED FRONT DRIVE AXLE CARRIER LUBRICANT INFORMATION	2005-12-07
05-01-38-012	EI05082 - LOSS OF BLOWER MOTOR SPEEDS EXCEPT FOR LOW SPEED OR INOPERATIVE	2006-11-02
05-01-38-012A	EI05082 - LOSS OF BLOWER MOTOR SPEEDS EXCEPT FOR LOW SPEED OR INOPERATIVE	2006-11-02
05-01-38-012B	EI05082 - LOSS OF BLOWER MOTOR SPEEDS EXCEPT FOR LOW SPEED OR INOPERATIVE	2006-11-02
05-01-38-012C	EI05082 - LOSS OF BLOWER MOTOR SPEEDS EXCEPT FOR LOW SPEED OR INOPERATIVE	2006-11-02
05-02-32-008	EI06002 670 GEAR BOX POWER STEERING PUMP, P/S PERFORMANCE CONCERNS	2006-07-20
05-02-32-008A	EI06002 670 GEAR BOX POWER STEERING PUMP, P/S PERFORMANCE CONCERNS	2006-07-20
05-03-07-009	WHEEL ALIGNMENT SPECIFICATIONS, REQUIREMENTS AND RECOMMENDATIONS FOR GM VEHICLES	2006-09-28
05-03-07-009A	WHEEL ALIGNMENT SPECIFICATIONS, REQUIREMENTS AND RECOMMENDATIONS FOR GM VEHICLES	2006-09-28
05-03-08-002	REPLACEMENT OF SHOCK ABSORBERS AND STRUTS AND USE OF LABOR OPERATIONS E3800, E3801, E3807, E5800, E5801, E5807, E5850, E3857, E5750, E5751 AND E5757 (LABOR OPERATIONS 7611101, 7611102, 7611103, 7613101, 7613102 AND 7613103 FOR SAAB	2006-07-28
05-03-08-002A	REPLACEMENT OF SHOCK ABSORBERS AND STRUTS AND USE OF LABOR OPERATIONS E3800, E3801, E3807, E5800, E5801, E5807, E5850, E3857, E5750, E5751 AND E5757 (LABOR OPERATIONS 7611101, 7611102, 7611103, 7613101, 7613102 AND 7613103 FOR SAAB	2006-07-28
05-03-08-006	SMU - REVISED STABILIZER SHAFT LINK REPLACEMENT PROCEDURE AND FASTENER TIGHTENING SPECIFICATIONS	2005-04-12
05-03-10-003	LOW TIRE PRESSURE LEAKING CAST ALUMINUM WHEELS (REPAIR WITH ADHESIVE SEALANT)	2005-12-19
05-03-10-003A	LOW TIRE PRESSURE LEAKING CAST ALUMINUM WHEELS (REPAIR WITH ADHESIVE SEALANT)	2005-12-19
05-03-10-004	TIRE PRESSURE MONITORING (TPM) SYSTEM - TIRE MOUNTING AND DISMOUNTING	2005-04-19

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 18

© 2005 Mitchell Repair Information Company, LLC.

# 2004 Chevrolet Tahoe

All TSBs

05-03-10-005	HANDLING CHARACTERISTICS OF VEHICLES WITH 20 INCH WHEEL/TIRE ASSEMBLIES	2005-04-20
05-03-10-012	USE RECOMMENDED TIRE MOUNTING LUBRICANT TO PREVENT TIRES FROM SLIPPING ON CHROME WHEELS	2005-09-16
05-03-10-020	USE OF NITROGEN GAS IN TIRES	2005-12-05
05-03-16-002	TIRE PRESSURE MONITORING (TPM) SYSTEM - SYSTEM MESSAGES	2005-06-20
05037	SECOND ROW CENTER SAFETY BELT	2005-07-14
05-04-21-002	GUIDELINES FOR REPLACEMENT OF TRANSFER CASE CONTROL MODULE (TCCM)	2005-03-10
05-04-21-003	SERVICE 4WD LIGHT ILLUMINATED, DTC C0374 SET (INSPECT WIRING HARNESS TO TRANSFER CASE SPEED SENSORS, REPLACE WIRING HARNESS)	2005-06-27
05-04-21-005	FIRST AND SECOND DESIGN CLUTCH HUB AND APPLY PLATE FOR NV246 TRANSFER CASE	2005-08-03
05-05-22-001	INFO - ON-CAR BRAKE LATHE SPECIFICATIONS AND MAINTENANCE REQUIREMENTS	2005-06-08
05-05-25-003	SERVICE STABILITY MESSAGE ON, DIAGNOSTIC TROUBLE CODE (DTC) C0131, C0196, C0290 AND/OR C0292 SET (INSPECT/REPLACE YAW RATE SENSOR/LATERAL ACCELEROMETER AND REPROGRAM ELECTRONIC BRAKE CONTROL MODULE)	2006-02-22
05-05-25-003A	SERVICE STABILITY MESSAGE ON, DIAGNOSTIC TROUBLE CODE (DTC) C0131, C0196, C0290 AND/OR C0292 SET (INSPECT/REPLACE YAW RATE SENSOR/LATERAL ACCELEROMETER AND REPROGRAM ELECTRONIC BRAKE CONTROL MODULE)	2006-02-22
05-05-25-003B	SERVICE STABILITY MESSAGE ON, DIAGNOSTIC TROUBLE CODE (DTC) C0131, C0196, C0290 AND/OR C0292 SET (INSPECT/REPLACE YAW RATE SENSOR/LATERAL ACCELEROMETER AND REPROGRAM ELECTRONIC BRAKE CONTROL MODULE)	2006-02-22
05-05-25-008	SERVICE STABILITRAK MESSAGE OR INTERMITTENT STABILITRAK ACTIVATION DURING NORMAL DRIVING, DTC C0455 (INSPECT/REPAIR STEERING WHEEL POSITION SENSOR (SWPS) CONNECTOR AND REPROGRAM EBCM)	2005-10-05
05060	WARRANTY COVERAGE AND PROCEDURES FOR JOE GIBBS PERFORMANCE (JGP) VEHICLES (CORPORATE SERVICE BULLETIN 05-00-89-024)	2005-07-18
05-06-01-006	ENGINE VIBRATION/NOISE AT IDLE, VIBRATION FELT IN STEERING WHEEL/SEAT (REPROGRAM PCM)	2005-02-09
05-06-01-010	SERVICE INFORMATION ON CONSOLIDATING THE USE OF LIQUID GASKET ENGINE SEALANTS	2005-03-07
05-06-01-014	OIL LEAK UNDER EXTREME COLD TEMPERATURES (-34 DEGREES CELSIUS, 30 DEGREES FAHRENHEIT OR COLDER) (INSTALL VENTED OIL FILL CAP)	2005-05-09
05-06-01-019C	ENGINE OIL LEAK AT CRANKSHAFT REAR MAIN OIL SEAL (INSTALL REVISED CRANKSHAFT REAR MAIN OIL SEAL USING REVISED REAR MAIN SEAL INSTALLER)	2006-05-12
05-06-01-019D	ENGINE OIL LEAK AT CRANKSHAFT REAR MAIN OIL SEAL (INSTALL REVISED CRANKSHAFT REAR MAIN OIL SEAL USING REVISED REAR MAIN SEAL INSTALLER)	2006-05-12
05-06-02-001	INFORMATION ON ALUMINUM HEATER CORE AND/OR RADIATOR REPLACEMENT	2005-02-24
05-06-02-002	INFO - DEX-COOL COOLANT - NEW LEAK DETECTION DYE J-46366 - REPLACES J-29545-6	2006-08-31
05-06-02-002A	INFO - DEX-COOL COOLANT - NEW LEAK DETECTION DYE J-46366 - REPLACES J-29545-6	2006-08-31
05-06-02-006	INSTRUCTIONS FOR USING GE-47716 VAC-N-FILL COOLANT REFILL TOOL	2005-05-12

XXX

# 2004 Chevrolet Tahoe

All TSBs

05-06-03-002	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
05-06-03-002A	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
05-06-04-021	SMU - REVISED INSPECTION/MAINTENANCE (I/M) EVAPORATIVE EMISSION (EVAP) SYSTEM SET PROCEDURE	2005-03-11
05-06-04-024	SMU - REVISED DTC P1172 AND DTC P2636	2005-03-17
05-06-04-029A	FLEXIBLE FUEL (RPO L59) ROUGH IDLE, MISFIRE, MIL DTC P0300 (INSTALL INTAKE MANIFOLD GASKETS WITH TEAL GREEN GASKET MATERIAL)	2005-06-24
05-06-04-035	USAGE OF E85 FUELS IN GM VEHICLES	2005-05-23
05-06-04-035A	USAGE OF E85 FUELS IN GM VEHICLES	2006-05-31
05-06-04-035B	USAGE OF E85 FUELS IN GM VEHICLES	2006-05-31
05-06-04-043	FUEL CAP TETHER TOO SHORT TO HOOK ON FUEL DOOR WHILE FUELING VEHICLE (INSTALL FUEL FILLER HOUSING AND CAP)	2005-08-02
05-06-04-043A	FUEL CAP TETHER TOO SHORT TO HOOK ON FUEL DOOR WHILE FUELING VEHICLE (INSTALL FUEL FILLER HOUSING AND CAP)	2005-08-02
05-06-04-063	LM7, L59 OR L33 ENGINES WITH COLD START ROUGH OR INCORRECT IDLE, MISFIRE MALFUNCTION INDICATOR LAMP (MIL) OR FLASHING REQUIRING O2 SENSOR REPLACEMENT (REPROGRAM PCM)	2005-10-12
05-07-30-013	4L60-E/4L65-E AUTOMATIC TRANSMISSION SECOND GEAR START, LACK/LOSS OF POWER WHEN ACCELERATING FROM A STOP (REPROGRAM POWERTRAIN CONTROL MODULE (PCM))	2005-05-09
05-07-30-017	4L60-E/4L65-E/4L70-E AUTOMATIC TRANSMISSION/TORQUE CONVERTER CLUTCH (TCC) SHUDDER, WATER IN TRANSMISSION (REPAIR TRANSMISSION AND SEAL COWL AREA)	2006-02-17
05-07-30-017A	4L60-E/4L65-E/4L70-E AUTOMATIC TRANSMISSION/TORQUE CONVERTER CLUTCH (TCC) SHUDDER, WATER IN TRANSMISSION (REPAIR TRANSMISSION AND SEAL COWL AREA)	2006-02-17
05-07-30-017B	4L60-E/4L65-E/4L70-E AUTOMATIC TRANSMISSION/TORQUE CONVERTER CLUTCH (TCC) SHUDDER, WATER IN TRANSMISSION (REPAIR TRANSMISSION AND SEAL COWL AREA)	2006-02-17
05-08-110-003	INFORMATION ON CLEANING DISCOLORED PASSENGER SIDE AIR BAG COVER	2005-03-24
05-08-42-008	INFORMATION ON DAMAGED FOG LAMP HOUSINGS CAUSED BY INCORRECT REPLACEMENT BULB	2005-06-10
05-08-44-001	COMPACT DISC (CD) OR DVD PLAYER SKIPPING, INOPERATIVE, SLUGGISH AND/OR LONG SEARCH TIMES	2005-01-24
05-08-44-005	INFORMATION ON REAR SEAT HEADPHONE FOAM EAR PAD REPLACEMENT IF WORN OR DAMAGED	2005-02-11
05-08-44-024	WARRANTY ADMIN. - RETURN OR REIMBURSEMENT OF CUSTOMER OWNED CDS, DVDS, CASSETTE TAPES AND/OR CD MAGAZINES	2005-07-29
05-08-46-001	ONSTAR GENERATION 5 OR 6 (DIGITAL) SYSTEM INOPERATIVE/HAS NO POWER, LED LIGHT NOT ON	2006-10-19
05-08-46-001A	ONSTAR GENERATION 5 OR 6 (DIGITAL) SYSTEM INOPERATIVE/HAS NO POWER, LED LIGHT NOT ON	2006-10-19
05-08-46-001B	ONSTAR GENERATION 5 OR 6 (DIGITAL) SYSTEM INOPERATIVE/HAS NO POWER, LED LIGHT NOT ON	2006-10-19
05-08-46-001C	ONSTAR GENERATION 5 OR 6 (DIGITAL) SYSTEM INOPERATIVE/HAS NO POWER, LED LIGHT NOT ON	2006-10-19
05-08-46-004	ONSTAR PHONE NUMBER CONCERNS (PHONE NUMBER INCORRECT/ASSIGNED TO ANOTHER VEHICLE/PHONE) THAT	2006-02-22

XXX

## 2004 Chevrolet Tahoe

All TSBs

OCCUR DURING DIAGNOSIS OF ONSTAR SYSTEM		
05-08-46-004A	ONSTAR PHONE NUMBER CONCERNS (PHONE NUMBER INCORRECT/ASSIGNED TO ANOTHER VEHICLE/PHONE) THAT OCCUR DURING DIAGNOSIS OF ONSTAR SYSTEM	2006-02-22
05-08-46-005	ONSTAR LABOR OPERATION CODES	2005-12-09
05-08-46-005A	ONSTAR LABOR OPERATION CODES	2005-12-09
05-08-46-006	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-46-006A	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-46-006B	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-46-006C	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-46-006D	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-46-006E	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-46-006F	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-46-006H	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
05-08-48-001	WARRANTY ADMIN. - GUIDELINES FOR CLAIMING C0034 - WINDSHIELD REPLACEMENT	2005-01-31
05-08-50-008	INTERMITTENT HEATED SEATS INOPERATIVE, DTC B3941 SET (REPROGRAM DRIVER SEAT MODULE)	2005-08-19
05-08-50-012	UNWANTED/LOOSE SEAT MOVEMENT	2006-07-24
05-08-50-012A	UNWANTED/LOOSE SEAT MOVEMENT	2006-07-24
05-08-50-017	POWER FRONT SEAT (RPO AN3) SWITCH KNOBS LOOSE OR MISSING (REPLACE SWITCH KNOBS)	2005-12-14
05-08-51-008	BUMPS OR RUST COLORED SPOTS IN PAINT DUE TO RAIL OR IRON DUST (REMOVE RAIL DUST)	2006-05-17
05-08-51-008A	BUMPS OR RUST COLORED SPOTS IN PAINT DUE TO RAIL OR IRON DUST (REMOVE RAIL DUST)	2006-05-17
05-08-61-005	SMU - REVISED CROSSMEMBER/BODY MOUNT BOLT INSTALLATION INFORMATION	2005-04-29
05-08-64-029	INFO - POWER WINDOW REGULATOR NOW AVAILABLE SEPARATELY FROM MOTOR	2006-02-16
05-08-64-029A	INFO - POWER WINDOW REGULATOR NOW AVAILABLE SEPARATELY FROM MOTOR	2006-02-16
05-08-64-029B	INFO - POWER WINDOW REGULATOR NOW AVAILABLE SEPARATELY FROM MOTOR	2006-02-16
05-08-64-032	REAR DOOR GLASS SQUEAL WHEN ROLLING DOWN (REMOVE MATERIAL)	2005-10-24
05-08-64-038	RUBBING OR SCRATCHING NOISE WHEN FRONT DRIVER OR FRONT PASSENGER POWER WINDOWS ARE ACTIVATED (INSTALL NEW ANTI-NOISE SLEEVE ON WINDOW REGULATOR SUPPORT)	2005-11-21
05-09-41-001	SUPPLEMENTAL INFLATABLE RESTRAINT (SIR) LIGHT ON, DTCS B0026 AND/OR B0044 (INSPECT AND/OR REPLACE IP HARNESS TO INFLATABLE RESTRAINT STEERING WHEEL	2005-01-19

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 21

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

MODULE YELLOW 4-WAY CONNECTOR C221)		
05-09-41-001A	SUPPLEMENTAL INFLATABLE RESTRAINT (SIR) LIGHT ON, DTCS B0013, B0014, B0017, B0018, B0024, B0026, B0043, B0044 (INSPECT/REPLACE IP HARNESS TO INFLATABLE RESTRAINT MODULE YELLOW 4-WAY CONNECTOR C221/C222)	2006-01-30
05-09-41-010	NEW SIR SYSTEM DISABLING AND ENABLING PROCEDURE	2005-12-22
05-48-46-006G	INFORMATION ON UPGRADING CERTAIN ONSTAR GENERATION 4 AND 5 ANALOG/DIGITAL-READY SYSTEMS TO ONSTAR GENERATION 6 DIGITAL-CAPABLE SYSTEM	2006-11-01
06-00-89-024	CAR AND TRUCK "FIX IT RIGHT THE FIRST TIME" ISSUES	2006-11-01
06-00-89-024A	CAR AND TRUCK "FIX IT RIGHT THE FIRST TIME" ISSUES	2006-11-01
06-00-89-024B	CAR AND TRUCK "FIX IT RIGHT THE FIRST TIME" ISSUES	2006-11-01
06-00-89-024C	CAR AND TRUCK "FIX IT RIGHT THE FIRST TIME" ISSUES	2006-11-01
06-00-89-024D	CAR AND TRUCK "FIX IT RIGHT THE FIRST TIME" ISSUES	2006-11-01
06-00-89-024E	CAR AND TRUCK "FIX IT RIGHT THE FIRST TIME" ISSUES	2006-11-01
06-00-89-024F	CAR AND TRUCK "FIX IT RIGHT THE FIRST TIME" ISSUES	2006-11-01
06-00-89-026	CUSTOMER CONCERN NOT DUPLICATED/VERIFIED LABOR OPERATIONS	2006-05-18
06-00-89-031	ENGINE AND AUTOMATIC TRANSMISSION/TRANSAXLE IDENTIFICATION	2006-06-12
06-00-89-036	OWNER MANUAL AND WARRANTY INFORMATION IN SERVICE INFORMATION (SI) WEBSITE/DISTRIBUTED ON CD	2006-07-21
06-00-89-038	INFORMATION ON RADIO AND INSTRUMENT PANEL CLUSTER (IPC) PART RESTRICTIONS (U.S. ONLY)	2006-08-07
06-01-38-003	INTERMITTENT TICKING NOISE FROM I/P, POOR A/C PERFORMANCE, HVAC DTCS B0229, B0414, B0424, B3770, (REPROGRAM HVAC CONTROL MODULE)	2006-04-27
06-01-39-002	FRONT BLOWER MOTOR INOPERATIVE OR MAY NOT SHUT OFF IN EXTREMELY LOW AMBIENT TEMPERATURE CONDITIONS	2006-08-14
06-01-39-002A	FRONT BLOWER MOTOR INOPERATIVE OR MAY NOT SHUT OFF IN EXTREMELY LOW AMBIENT TEMPERATURE CONDITIONS	2006-08-14
06-01-39-007	CONTAMINATED R134A REFRIGERANT FOUND ON MARKET FOR AUTOMOTIVE AIR-CONDITIONING SYSTEMS	2006-07-25
06-02-32-013	DIAGNOSTIC TIPS/RECOMMENDATIONS WHEN POWER STEERING PUMP REPLACEMENT IS NECESSARY	2006-10-25
06-03-10-004	INFO - PROPER USE OF OEM SERVICE WHEEL WEIGHTS, MARRING AND/OR DAMAGE DUE TO USE OF NON-OEM AND/OR INCORRECT WHEEL WEIGHT INSTALLATION	2006-03-01
06-04-21-001	UPDATED TRANSFER CASE CONNECTOR SERVICE KIT NOW AVAILABLE FOR TRANSFER CASE SPEED SENSOR WIRE HARNESS CONNECTOR THAT COMES LOOSE OR CONNECTOR RETAINER CLIP BREAKS	2006-05-17
06-06-01-010	INFO ON CLOSE-COUPLED CONVERTER, ENGINE BREAKDOWN OR NON-FUNCTION DUE TO SEVERE OVERHEAT OR LACK OF OIL CAUSING PISTON, ROD, CRANKSHAFT, CYLINDER, HEAD, CAMSHAFT, INTAKE/EXHAUST VALVE, BEARING DAMAGE	2006-04-19
06-06-02-005	INFORMATION ON CONTACTING TECHNICAL ASSISTANCE FOR POOR ENGINE COOLING AND/OR A/C BLOWING WARM AIR WHEN VEHICLE IS IDLING OR MOVING AT LOW SPEEDS	2006-02-28
06-06-04-030	LOCATIONS OF E85 REFUELING STATIONS AND EXPANDED E85 INFORMATION	2006-05-15
06-06-04-035	USE OF E85 FUELS IN VEHICLES NOT CERTIFIED BY GM AS BEING FLEXFUEL COMPATIBLE / AFTERMARKET CONVERSION OF VEHICLES TO OPERATE ON E85 FUELS	2006-07-13
06-06-04-037	NORMAL CHARACTERISTICS OF MALFUNCTION INDICATOR LAMP (MIL) DURING ON-BOARD DIAGNOSTICS (OBD) INSPECTION/MAINTENANCE (I/M) TESTING	2006-08-04
06-06-04-046	INFORMATION ON ENGINE MISFIRE MIL/SES LIGHT ILLUMINATED OR FLASHING DTC P0300, P0301, P0302, P0303,	2006-09-12

XXX

## 2004 Chevrolet Tahoe

All TSBs

	P0304, P0305, P0306, P0307, P0308, P0420 OR P0430	
06-06-04-057	REVISED MASS AIR FLOW CORE RETURN REQUIREMENTS	2006-10-24
06-08-111-004	INFORMATION ON DISCOLORATION, BLISTERING, PEELING OR EROSION OF VARIOUS EXTERIOR EMBLEMS INCLUDING THE CHEVY BOWTIE	2006-09-08
06-08-42-002	SUNSHADE (VISOR) VANITY MIRROR BULB INOPERATIVE (REPLACE VANITY MIRROR BULB ONLY)	2006-02-09
06-08-43-003	WINDSHIELD WIPER PERFORMANCE, CLEANING INSTRUCTIONS AND MAINTENANCE	2006-06-30
06-08-44-012	DVD NAVIGATION UPDATE PROGRAM, AVN SOFTWARE UPDATE DISCS, AND ORDERING INFORMATION	2006-07-26
06-08-44-012A	DVD NAVIGATION UPDATE PROGRAM, AVN SOFTWARE UPDATE DISCS, AND ORDERING INFORMATION	2006-07-26
06-08-44-015	INFORMATION ON ELIMINATING NOISE IN AUDIO SYSTEM WHEN USING PORTABLE PLAYBACK DEVICE	2006-04-19
06-08-45-001	INFORMATION ON CHANGES TO THE SI TABLE OF CONTENTS, ELECTRICAL CONNECTORS, TERMINAL TESTING/REPAIR AND THE IMPORTANCE OF J-38125 TERMINAL REPAIR KIT MAINTENANCE	2006-02-17
06-08-45-004	INSTRUMENT PANEL (I/P), BODY AND GENERAL WIRING HARNESS REPAIR	2006-05-02
06-08-46-002	INFO - AVAILABILITY OF GM ONSTAR VEHICLE DIAGNOSTICS AND GM GOODWRENCH REMOTE DIAGNOSTIC SERVICES	2006-08-30
06-08-46-002A	INFO - AVAILABILITY OF GM ONSTAR VEHICLE DIAGNOSTICS AND GM GOODWRENCH REMOTE DIAGNOSTIC SERVICES	2006-08-30
06-08-47-001	WARRANTY, SPS, CONTROL MODULE DIAGNOSTICS AND CONFIGURATION INFORMATION, PROGRAMMING, SET-UP	2006-02-21
06-08-48-002	INFO - AVAILABILITY OF A NEW DESIGN BACK GLASS	2006-10-05
06-08-50-004	FRONT SEAT ARMREST HINGE BREAKING	2006-07-28
06-08-50-004A	FRONT SEAT ARMREST HINGE BREAKING	2006-07-28
06-08-50-009	INFORMATION ON PASSENGER OCCUPANT SENSING SYSTEM CONCERNS WITH CUSTOM UPHOLSTERY, ACCESSORY SEAT HEATERS OR OTHER COMFORT ENHANCING DEVICES	2006-08-17
06-08-61-003	UNDERBODY POP OR CLUNK TYPE NOISE WHILE TURNING OR DRIVING ON UNEVEN ROAD SURFACES	2006-09-25
06-08-61-003A	UNDERBODY POP OR CLUNK TYPE NOISE WHILE TURNING OR DRIVING ON UNEVEN ROAD SURFACES	2006-09-25
06-93-98	USE RECOMMENDED TIRE MOUNTING LUBRICANT TO PREVENT TIRES FROM SLIPPING ON CHROME WHEELS	2005-09-16
36-71-06B	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
40-05-01C	WARRANTY PARTS CENTER/CORPORATE PARTS RETURN PROGRAM	2005-06-20
43-17-01A	BUMPS OR RUST COLORED SPOTS IN PAINT DUE TO RAIL OR IRON DUST (REMOVE RAIL DUST)	2006-05-17
43-17-01B	BUMPS OR RUST COLORED SPOTS IN PAINT DUE TO RAIL OR IRON DUST (REMOVE RAIL DUST)	2006-05-17
43-64-07A	LOW VOLTAGE DISPLAY ON IP GAUGE, LIGHTS DIM AT STOP LIGHTS, BATTERY DISCHARGED, NO START, SLOW CRANKING, DIM LIGHTS AT IDLE, LOW GENERATOR OUTPUT	2004-07-28
48-05-01C	CUSTOMER CONCERN NOT DUPLICATED/VERIFIED LABOR OPERATIONS	2006-05-18
56-44-01	INFORMATION ON DRIVELING CLUNK NOISE WHEN SHIFTING BETWEEN PARK AND DRIVE, PARK AND REVERSE OR DRIVE AND REVERSE	2006-06-08
56-44-01A	INFORMATION ON DRIVELING CLUNK NOISE WHEN SHIFTING BETWEEN PARK AND DRIVE, PARK AND REVERSE OR DRIVE AND REVERSE	2006-06-08

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 23

© 2005 Mitchell Repair Information Company, LLC.

## 2004 Chevrolet Tahoe

All TSBs

60-05-02	GM NEW VEHICLE TIRE WARRANTY PROGRAM	2005-06-17
72-05-04	WARRANTY ADMIN. - GUIDELINES FOR CLAIMING C0034 - WINDSHIELD REPLACEMENT	2005-01-31
72-05-12	REPLACEMENT OF SHOCK ABSORBERS AND STRUTS AND USE OF LABOR OPERATIONS E3800, E3801, E3807, E5800, E5801, E5807, E5850, E3857, E5750, E5751 AND E5757 (LABOR OPERATIONS 7611101, 7611102, 7611103, 7613101, 7613102 AND 7613103 FOR SAAB	2006-07-28
73-62-13A	INFORMATION ON ALUMINUM HEATER CORE AND/OR RADIATOR REPLACEMENT	2005-02-24
736214	DEX-COOL ENGINE COOLANT INFORMATION	2005-02-13
73-62-14	DEX-COOL ENGINE COOLANT INFORMATION	2005-02-13
83-12-21	CONTAMINATED R-134A A/C SYSTEMS - AIR CONDITIONING SYSTEM FLUSHING PROCEDURES AND UNIVERSAL IN-LINE A/C FILTER INSTALLATION	2004-09-14
83-35-08	CHEMICAL STAINING, PITTING, CORROSION AND/OR SPOTTED APPEARANCE OF CHROMED ALUMINUM WHEELS	2006-08-01
83-64-17	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
87-61-24	USE OF SURFACE CONDITIONING DISKS	2006-01-18
93-169-3E	USE RECOMMENDED TIRE MOUNTING LUBRICANT TO PREVENT TIRES FROM SLIPPING ON CHROME WHEELS	2005-09-16
93-263-3E	LOW TIRE PRESSURE LEAKING CAST ALUMINUM WHEELS (REPAIR WITH ADHESIVE SEALANT)	2005-12-19
93-3-11	USE RECOMMENDED TIRE MOUNTING LUBRICANT TO PREVENT TIRES FROM SLIPPING ON CHROME WHEELS	2005-09-16
93-3-6	USE RECOMMENDED TIRE MOUNTING LUBRICANT TO PREVENT TIRES FROM SLIPPING ON CHROME WHEELS	2005-09-16
93-3E-63	USE RECOMMENDED TIRE MOUNTING LUBRICANT TO PREVENT TIRES FROM SLIPPING ON CHROME WHEELS	2005-09-16
93-U-57	LOW TIRE PRESSURE LEAKING CAST ALUMINUM WHEELS (REPAIR WITH ADHESIVE SEALANT)	2005-12-19
99-00-89-011	KEY CODE INFORMATION	2006-10-10
99-00-89-011A	KEY CODE INFORMATION	2006-10-10
99-00-89-011B	KEY CODE INFORMATION	2006-10-10
99-00-89-015	LIGHT SERVICE SUPPORT VEHICLE LSSV AND ENHANCED MOBILITY PACKAGE EMP - RPO EM7 VEHICLE (FORMERLY COMMERCIAL UTILITY CARGO VEHICLE - CUCV II AND III) SERVICE (U.S. ONLY)	2005-09-21
99-00-89-015A	LIGHT SERVICE SUPPORT VEHICLE LSSV AND ENHANCED MOBILITY PACKAGE EMP - RPO EM7 VEHICLE (FORMERLY COMMERCIAL UTILITY CARGO VEHICLE - CUCV II AND III) SERVICE (U.S. ONLY)	2005-09-21
99-00-89-015B	LIGHT SERVICE SUPPORT VEHICLE LSSV AND ENHANCED MOBILITY PACKAGE EMP - RPO EM7 VEHICLE (FORMERLY COMMERCIAL UTILITY CARGO VEHICLE - CUCV II AND III) SERVICE (U.S. ONLY)	2005-09-21
99-00-89-015C	LIGHT SERVICE SUPPORT VEHICLE LSSV AND ENHANCED MOBILITY PACKAGE EMP - RPO EM7 VEHICLE (FORMERLY COMMERCIAL UTILITY CARGO VEHICLE - CUCV II AND III) SERVICE (U.S. ONLY)	2005-09-21
99-00-89-015D	LIGHT SERVICE SUPPORT VEHICLE LSSV AND ENHANCED MOBILITY PACKAGE EMP - RPO EM7 VEHICLE (FORMERLY COMMERCIAL UTILITY CARGO VEHICLE - CUCV II AND III) SERVICE (U.S. ONLY)	2005-09-21
99-00-89-015E	LIGHT SERVICE SUPPORT VEHICLE LSSV AND ENHANCED MOBILITY PACKAGE EMP - RPO EM7 VEHICLE (FORMERLY COMMERCIAL UTILITY CARGO VEHICLE - CUCV II AND III) SERVICE (U.S. ONLY)	2005-09-21

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 24

© 2005 Mitchell Repair Information Company, LLC.



## 2004 Chevrolet Tahoe

All TSBs

99-00-89-019	WARRANTY PARTS CENTER/CORPORATE PARTS RETURN PROGRAM	2005-06-20
99-00-89-019A	WARRANTY PARTS CENTER/CORPORATE PARTS RETURN PROGRAM	2005-06-20
99-00-89-019B	WARRANTY PARTS CENTER/CORPORATE PARTS RETURN PROGRAM	2005-06-20
99-00-89-019C	WARRANTY PARTS CENTER/CORPORATE PARTS RETURN PROGRAM	2005-06-20
99-01-38-006A	J-43600 ACR 2000 ESSENTIAL REFRIGERANT RECOVERY/RECHARGE EQUIPMENT	2004-06-22
99-01-38-006B	J-43600 ACR 2000 ESSENTIAL REFRIGERANT RECOVERY/RECHARGE EQUIPMENT	2004-06-22
99-04-20-002	INFORMATION ON DRIVELING CLUNK NOISE WHEN SHIFTING BETWEEN PARK AND DRIVE, PARK AND REVERSE OR DRIVE AND REVERSE	2006-06-08
99-04-20-002A	INFORMATION ON DRIVELING CLUNK NOISE WHEN SHIFTING BETWEEN PARK AND DRIVE, PARK AND REVERSE OR DRIVE AND REVERSE	2006-06-08
99-04-20-002B	INFORMATION ON DRIVELING CLUNK NOISE WHEN SHIFTING BETWEEN PARK AND DRIVE, PARK AND REVERSE OR DRIVE AND REVERSE	2006-06-08
99-04-20-002C	INFORMATION ON DRIVELING CLUNK NOISE WHEN SHIFTING BETWEEN PARK AND DRIVE, PARK AND REVERSE OR DRIVE AND REVERSE	2006-06-08
99-04-20-002D	INFORMATION ON DRIVELING CLUNK NOISE WHEN SHIFTING BETWEEN PARK AND DRIVE, PARK AND REVERSE OR DRIVE AND REVERSE	2006-06-08
99-06-03-012	INFO - BATTERY AND CHARGING SYSTEM ELECTRICAL DIAGNOSTICS	2005-07-01
99-07-30-020	PRODUCT QUALITY CENTER FOR ENGINE AND TRANSMISSION ASSEMBLY AND TRANSFER CASE REPLACEMENT	2006-06-28
99-07-30-022	SHIFT STABILIZATION AND TOW/HAUL MODE FEATURE FOR HYDRA-MATIC	2003-06-05
99-07-30-022A	SHIFT STABILIZATION AND TOW/HAUL MODE FEATURE FOR HYDRA-MATIC	2003-06-05
99-08-51-001A	PAINT-LESS DENT REPAIR PROCESS	2005-11-21
99-08-51-007	REFINISHING ALUMINUM WHEELS	2006-06-19
99-08-51-007A	REFINISHING ALUMINUM WHEELS	2006-06-19
99-08-51-007B	REFINISHING ALUMINUM WHEELS	2006-06-19
99-08-51-007C	REFINISHING ALUMINUM WHEELS	2006-06-19
99-08-52-005	REMOTE KEYLESS ENTRY OPERATIONAL CHARACTERISTICS	2006-01-10
99-08-52-005A	REMOTE KEYLESS ENTRY OPERATIONAL CHARACTERISTICS	2006-01-10
99-08-52-005B	REMOTE KEYLESS ENTRY OPERATIONAL CHARACTERISTICS	2006-01-10
99-09-40-005	SEAT BELT EXTENDER AVAILABILITY	2005-11-23
99-09-40-005A	SEAT BELT EXTENDER AVAILABILITY	2005-11-23
99-09-40-005B	SEAT BELT EXTENDER AVAILABILITY	2005-11-23
99-09-40-005C	SEAT BELT EXTENDER AVAILABILITY	2005-11-23
T-93-93	USE RECOMMENDED TIRE MOUNTING LUBRICANT TO PREVENT TIRES FROM SLIPPING ON CHROME WHEELS	2005-09-16
VSS20020131	INOPERATIVE 4WD/AWD OR SERVICE 4WD INDICATOR	2004-03-01
VSS20040074	BRAKE WARRANTY SERVICE AND PROCEDURES	2006-06-01
VSS20040091	FUEL CAP TETHER STRAP TOO SHORT	2004-04-13
VSS20040205	POWER SEAT WILL NOT RETAIN PRESET MEMORY POSITION	2004-08-03
VSS20040231	POWER SEAT WILL NOT RETAIN PRESET MEMORY POSITION	2004-08-23
VSS20050398	GMT 800 IP CLUSTERS	2005-02-08

XXX

Saturday, October 10, 2009 1:34:09 AM

Page 25

© 2005 Mitchell Repair Information Company, LLC.